


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 O/P / WS / P / RES / OD / RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehl _____

Veh No: SMV 9684G Yr Regn: 11/4/21
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Tractor or _____
 Make: Mitsubishi Outlander C.B. 1998
 Colour: White A/O: Insured / Std / NI / N
 Sp. Reading: 5498 YR Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: GF 7w 972139
 Gen. Cond: Good / Fair / Poor / Bunt
 Steering: In order / Jammed / Locked / Burnt or
 Brake: In order / Jammed / Locked / Burnt or
 Mod: NII / SRim / STD A/Rim or
 Tyre Size: P1 225/55R8
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Toyo
 Front R/Bal. 5 mm Rear R/Bal. 5 mm
 L/Bal. 5 mm U/Bal. 5 mm
 D.O.A. 25/10/21 Car Pro O.O.I. 29/10/21
 Survey hold of _____
 Des. of Damages: FR / Rear / O/S / N/S / VIC / Roof/ceiling

(Policy Condition)
 Remark: The veh had submitted its
 repair at the time of inspection.



Del. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 SIA / PR Seen _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Cum Sum: _____ % 3 Vol.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The V/S / O/S / N/S frame / Body structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-118K</u>
	<u>finalize \$9550 (L/S, before GST). 10 repair days</u>
	<u>red: 7498.40; 43%</u>

Time, File, Report
 : Prel. Report
 : Final Report

Days Of Repair: 10
 Resurvey No. of Trips: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Insp (\$ _____)
 : Wheel and (\$ _____)

Survey Fee
Transportation
S + NS, SI
Excess
Others
TOTAL

**Adjustment of Spare Parts Costs for Repairs SMY 9684G
MITSUBISHI OUTLANDER 2.0**

Item	Qty	Vehicle parts description	\$
1	1	Rear bumper / <i>DD</i>	1020.00
3	2	rear bumper LH & RH bracket ?	180.00
4	1	rear bumper lower diffuser garnish / <i>DD</i>	395.00
5	2	rear bumper reflector lamp LH& RH ?	230.00
6	2	Rear bumper side retainer LH & RH / <i>BR</i>	155.00
7	1 set	Rear bumper fasteners / <i>nc</i>	38.00 <i>30</i>
8	1	Tailgate / <i>DD</i>	1050.00
9	1	Tailgate center chrome garnish ?	485.00
10	1 set	Tailgate center garnish fasteners ?	32.00
11	1	Tailgate lock acurator / <i>nc</i> (photo) ?	450.00
12	1	Tailgate outlander emblem	95.00
13	1	Tailgate logo emblem / <i>nc</i>	80.00
14	1	tailgate C&C emblem / <i>nc</i>	70.00
15	1	Tailgate inner trim board ?	360.00
16	1 set	Tailgate inner trim clips ?	38.00
17	1	Tailgate weatherstrip / <i>nc</i> (Ru (photo))	295.00
18	1	Tailgate inner lock ?	435.00
19	2	tailgate lamp LH & RH / <i>cut</i>	820.00
20	2	tailgate absorber LH & RH <i>x</i>	400.00
21	1	tailgate wiper assy <i>x</i>	450.00
22	2	tailgate rubber stopper LH & RH <i>x</i>	60.00
23	1	Rear windscreen <i>x</i>	980.00
24	1	rear windscreen moulding / <i>nc</i>	165.00
25	1	Taillamp LH & RH assy / <i>cut</i>	1180.00
26	2 set	Taillamp assy fastners LH & RH ?	36.00
27	1	Rear end panel / <i>DD</i> (photo)	400.00
28	1	Rear end panel top garnish / <i>cut</i>	190.00
29	1 set	Rear end panel top garnish fasteners / <i>nc</i>	22.00 <i>15</i>
30	1	Rear spare tyre panel / <i>DD</i> (photo)	1300.00
31	1	Rear spare tyre board / <i>BR</i>	320.00
32	2	rear fender inner trim board LH & RH / <i>BR</i>	1200.00
33	2	rear fender inner sheild LH & RH <i>x</i>	260.00
34	1	rear spare tyre tools box assy ? (photo)	255
35	1	Exhaust muffler / <i>DD</i> (photo)	580.00
36	2	end panel air vent bracket LH & RH <i>x</i>	150.00
			<hr/> 14176.00
			1417.6
		Less 10%	<hr/> 12758.40
		Special nett item	
1	1	Rear number plate w casing <i>x</i>	60.00
1	1	Rear windscreen sealant / <i>nc</i>	60.00 <i>40</i>

1	Rear end panel sealant	✓ <i>MP</i>	60.00	<i>30</i>
1	spare tyre panel sealant	✓ <i>MP</i>	60.00	<i>30</i>
1	Reverse sensor	✓ <i>BR</i>	200.00	
1	reverse camera	?	350.00	
1	Rear floor panel insulation pad	✓ <i>MP</i>	150.00	<i>50</i>
	Total parts		940.00	

Adjustment of Labour Costs for Repairs

Spraying of affected areas	1200.00	<i>1000</i>
Carry out body cavity preservation	150.00	<i>30</i>
To remove & replaced damaged parts including straightening & repositioning replacement parts & panel beat	1000.00	<i>900</i>
Remove & refix rear windscreen	150.00	<i>120</i>
Check wiring	80.00	<i>30</i>
Remove/refix boot compartment fittings & attachments for	80.00	<i>50</i>
remove & refix reverse camera	100.00	<i>30</i>
Remove & refix reverse sensor	80.00	<i>30</i>
To remove & refix exhaust	100.00	<i>50</i>
Remove & refix tailgate components	80.00	<i>50</i>
Remove & reinstall rear boot upholstery & vaccum inner	80.00	<i>50</i>
to straighten rear chassis member	250.00	<i>?</i>
Total labour	3350.00	

Steve (LKK)
29/10/21, 11.00am

MR PIL
LIS
By AL sy
10 days

LKKA Auto Compensation - Insurance notify the Rep the following:

- To resurvey after after spray painting
- To display damaged parts during resurvey
- Parts prices must be subject to information
- Third party survey on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repater
 Signature:
 Date: