

**Adjustment of Spare Parts Costs for Repairs SMY 9684G
MITSUBISHI OUTLANDER 2.0**

Item	Qty	Vehicle parts description	\$
1	1	Rear bumper / DD	1020.00 -
3	2	rear bumper LH & RH bracket ? - BT	180.00 -
4	1	rear bumper lower diffuser garnish / DD	395.00 360 -
5	2	rear bumper reflector lamp LH& RH ? - BR	230.00 200 -
6	2	Rear bumper side retainer LH & RH - BR	155.00 -
7	1 set	Rear bumper fasteners - nec	38.00 30 -
8	1	Tailgate / DD	1050.00 989 -
9	1	Tailgate center chrome garnish ? - BR	485.00 -
10	1 set	Tailgate center garnish fasteners ? - nec	32.00 10 -
11	1	Tailgate lock acurator - nec (photo) ? - BT	450.00 -
12	1	Tailgate outlander emblem ? - nec	95.00 -
13	1	Tailgate logo emblem - nec	80.00 -
14	1	tailgate C&C emblem - nec	70.00 -
15	1	Tailgate inner trim board ? - BR	360.00 -
16	1 set	Tailgate inner trim clips ? - nec	38.00 15 -
17	1	Tailgate weatherstrip - (Ru)	295.00 213 -
18	1	Tailgate inner lock ? (photo) - BT	435.00 -
19	2	tailgate lamp LH & RH - cut	820.00 -
20	2	tailgate absorber LH & RH x nn	400.00
21	1	tailgate wiper assy x nn	450.00
22	2	tailgate rubber stopper LH & RH x nn	60.00
23	1	Rear windscreen x nn	980.00
24	1	rear windscreen moulding - nec	165.00 -
25	1	Taillamp LH & RH assy - cut	1180.00 -
26	2 set	Taillamp assy fastners LH & RH ? x nn	36.00
27	1	Rear end panel / DD (photo)	400.00 326 -
28	1	Rear end panel top garnish - cut	190.00 113 -
29	1 set	Rear end panel top garnish fasteners - nec	22.00 15 -
30	1	Rear spare tyre panel / DD (photo)	1300.00 751 -
31	1	Rear spare tyre board - BR	320.00 -
32	2	rear fender inner trim board LH & RH (RH) - BR	1200.00 600 -
33	2	rear fender inner sheild LH & RH x nn	260.00
34	1	rear spare tyre tools box assy ? (photo) - BR	255 -
35	1	Exhaust muffler / DD (photo)	580.00 -
36	2	end panel air vent bracket LH & RH x nn	150.00

10%
 20%
 Less 10%

10,272.00
 - 20% 10%
 8217.60
 9244.80

14176.00
 1417.6
 12758.40

Special nett item		
1	Rear number plate w casing x nn	60.00
1	Rear windscreen sealant - nec	60.00 40

1	Rear end panel sealant	✓ n/c	60.00	30	
1	spare tyre panel sealant	✓ n/c	60.00	30	
1	Reverse sensor	✓ BR	200.00	-	
1	reverse camera	1 x nn	350.00		
1	Rear floor panel insulation pad	2 n/c	150.00	50	350 -
	Total parts		<u>940.00</u>		

Adjustment of Labour Costs for Repairs

Spraying of affected areas	1200.00	1000	
Carry out body cavity preservation	150.00	30	
To remove & replaced damaged parts including straightening & repositioning replacement parts & panel beat	1000.00	900	
Remove & refix rear windscreen	150.00	120	
Check wiring	80.00	30	
Remove/refix boot compartment fittings & attachments for	80.00	50	
remove & refix reverse camera	100.00	30	
Remove & refix reverse sensor	80.00	30	
To remove & refix exhaust	100.00	50	
Remove & refix tailgate components	80.00	50	
Remove & reinstall rear boot upholstery & vaccum nner	80.00	50	
to straighten rear chassic member	250.00	1 x	
Total labour	3350.00		= 10,907.60

Steve (LKK)
29/10/21, 11.9000

MR PIL
L/S
By AL dy
10 dys
= 15,8726.00
= 8750
11,934.80
L/S-9547.84
= 9550

LKKA Auto Centre will advise and notify the Repairer of the following:

- To resurvey and refinish after spray painting
- To display damaged parts during resurvey
- Parts prices must be subject to quotation
- Third party survey on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: