



**Adjustment of Spare Parts Costs for Repairs SMY 9684G  
MITSUBISHI OUTLANDER 2.0**

Item	Qty	Vehicle parts description	\$
1	1	Rear bumper / <i>DD</i>	1020.00
3	2	rear bumper LH & RH bracket ?	180.00
4	1	rear bumper lower diffuser garnish / <i>DD</i>	395.00
5	2	rear bumper reflector lamp LH& RH ?	230.00
6	2	Rear bumper side retainer LH & RH / <i>BR</i>	155.00
7	1 set	Rear bumper fasteners / <i>nc</i>	38.00 <i>30</i>
8	1	Tailgate / <i>DD</i>	1050.00
9	1	Tailgate center chrome garnish ?	485.00
10	1 set	Tailgate center garnish fasteners ?	32.00
11	1	Tailgate lock acurator / <i>nc</i> (photo) ?	450.00
12	1	Tailgate outlander emblem	95.00
13	1	Tailgate logo emblem / <i>nc</i>	80.00
14	1	tailgate C&C emblem / <i>nc</i>	70.00
15	1	Tailgate inner trim board ?	360.00
16	1 set	Tailgate inner trim clips ?	38.00
17	1	Tailgate weatherstrip / <i>nc</i> (Ru (photo))	295.00
18	1	Tailgate inner lock ? (photo)	435.00
19	2	tailgate lamp LH & RH / <i>cut</i>	820.00
20	2	tailgate absorber LH & RH <i>x</i>	400.00
21	1	tailgate wiper assy <i>x</i>	450.00
22	2	tailgate rubber stopper LH & RH <i>x</i>	60.00
23	1	Rear windscreen <i>x</i>	980.00
24	1	rear windscreen moulding / <i>nc</i>	165.00
25	1	Taillamp LH & RH assy / <i>cut</i>	1180.00
26	2 set	Taillamp assy fastners LH & RH ?	36.00
27	1	Rear end panel / <i>DD</i> (photo)	400.00
28	1	Rear end panel top garnish / <i>cut</i>	190.00
29	1 set	Rear end panel top garnish fasteners / <i>nc</i>	22.00 <i>15</i>
30	1	Rear spare tyre panel / <i>DD</i> (photo)	1300.00
31	1	Rear spare tyre board / <i>BR</i>	320.00
32	2	rear fender inner trim board LH & RH / <i>BR</i>	1200.00
33	2	rear fender inner sheild LH & RH <i>x</i>	260.00
34	1	rear spare tyre tools box assy ? (photo)	255
35	1	Exhaust muffler / <i>DD</i> (photo)	580.00
36	2	end panel air vent bracket LH & RH <i>x</i>	150.00
			<hr/>
			14176.00
			1417.6
			<hr/>
			12758.40
Less 10%			
<b>Special nett item</b>			
1	1	Rear number plate w casing <i>x</i>	60.00
1	1	Rear windscreen sealant / <i>nc</i>	60.00 <i>40</i>

1	Rear end panel sealant	✓ <i>MP</i>	60.00	<i>30</i>
1	spare tyre panel sealant	✓ <i>MP</i>	60.00	<i>30</i>
1	Reverse sensor	✓ <i>BR</i>	200.00	
1	reverse camera	?	350.00	
1	Rear floor panel insulation pad	✓ <i>MP</i>	150.00	<i>50</i>
	<b>Total parts</b>		<b>940.00</b>	

**Adjustment of Labour Costs for Repairs**

Spraying of affected areas	1200.00	<i>1000</i>
Carry out body cavity preservation	150.00	<i>30</i>
To remove & replaced damaged parts including straightening & repositioning replacement parts & panel beat	1000.00	<i>900</i>
Remove & refix rear windscreen	150.00	<i>120</i>
Check wiring	80.00	<i>30</i>
Remove/refix boot compartment fittings & attachments for	80.00	<i>50</i>
remove & refix reverse camera	100.00	<i>30</i>
Remove & refix reverse sensor	80.00	<i>30</i>
To remove & refix exhaust	100.00	<i>50</i>
Remove & refix tailgate components	80.00	<i>50</i>
Remove & reinstall rear boot upholstery & vaccum inner	80.00	<i>50</i>
to straighten rear chassis member	250.00	<i>?</i>
<b>Total labour</b>	<b>3350.00</b>	

*Steve (LKK)*  
*29/10/21, 11.00am*

*MR PIL*  
*LIS*  
*By AL sy*  
*10 days*

**LKK Auto Centre** Insurance notify the Rep the following:

- To resurvey after after spray painting
- To display damaged parts during resurvey
- Parts prices must be subject to quotation
- Third party survey on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repater  
 Signature:  
 Date: