ASS. REC. BY:	21011064/14
Kenneth CS/CTI21011064/KTY3 ASS	GIGNMENT
From: Date:	Cont 201
Estimated Cost:	Veh No: Sn7 3804 Tyr Regn: 01, 11 Type: M.Car M. Cycle / Bus (Ver 1)
OD TP / WS / TP RES / OD RES / EVA / INV / MY	Lony / Taxl / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
at Workshop m/s Ping Auto	Make: Volkeneger Golf Rcc 1984
of Viny Hoto	Colour M. Cray A/C: Insured/Std/NI/NA
Insured:	Sp.Reading 170877 T/Radio: Insured / Std / NI / NA
Policy NoDMPCSNW00079542100	Eng/No:
Claims No. <u>SNM21D206127/C01/CHNGPW</u>	CANO: WVW3771K 88W130290
Cum la 1	Oon, Oon, Bood / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Brake: Ingree / Jammed / Leaked / Burnt or
	Modi: NII JATRIm I STD AJRIM or
(Policy Condition)	Tyre Size: F: 235/40R18
Remark: The veh had commenced its	R:
repair at the time of inspection.	BS / DUN / EXNOVA / EXT FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or
Bal. or Market Value: 8110k	
IDAC Accident Rport: Consistent? : Yes or No	Front Rear
GIA / PR Seen: Consistent?: Yes or No	mm RVBa'. 7 mm
Est. Repairs: 4-5 days Res.: Yes or No	mm Usa. 7 mm
Lum Sum: 1.B. 1 % 3 Val.: Yes or No	D.O.A. <u>04/10/1/</u> D.O.I. <u>29/10/2021</u> Survey held at
CA / REV / REP. J 24 HRS	
(18/2/) Vehicle: IN (OUT	Des. of Damages: Frt Rear O/S N/S U/C Rooftop or Under Can'ge
	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
201 Check reer danger.	
29/10 Wesp Soil no Space parts in	local markey of this mumer
part by part \$18222.20,	/
(1EU. 11929.00,03/0)	
	30151.8
Date/Time, File Pass to? : Prell. Report Da	evs Of Renair. 5
. Trem. Report	your ropan.
Dute/Fine, File Return to?	Survey No. of Trip: Survey Fee:
Add Fee:	Transportation:
Add P66: [: Site Insp (\$)s -Rssi
	: Interview (\$) Farts
Report Format:	Tech Invs (\$) Others
Lump Sum / I.B.1: (\$	Weekend (\$
	TOTAL

Ding Auto Pte Ltd Sin Ming Industrial Est. Sec C, Blk 10,#01-20 575645

Insurer Reference:

Repairer Reference: 044185

Date calculated: 27/10/2021 4:00 PM

Full Report

Registration: SMT3804T

Printed: 27/10/2021 4:01 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

Printed by:

Claim Reference:

Estimated Repair Time:

Ding Auto

Currency:

(Singapore) Pte Ltd SGD

21

21

Date of Incident: Hire Car Start:

Hire Car End:

24/10/21

Mhicle Details

Actual Repair Days:

Vehicle

Manufacturer:

Model:

Sub Model:

GOLF (5K)

VW

Model Sheet Number:

06 AF 06

Registration:

SMT3804T

VIN number: Odometer:

170877

Model Specs

5-DOOR

2.0 LTR 199KW

Not Notherson
1.B.1
Ex 81000

icle Condition


icle Status

-Accident Damage: te of Inspection:

amage Areas

All Underbody







Tyres Condition

Tyre Brand

Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right

Condition

mm

mm

mm

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

Labour

Labour		Prince of the second se	
	Time Base 10 WU/h	Price = 42.	00 SGD/h
Code	Description	WU	Price SGD
10 55 50	RENEW CONSOLE (COMPOSITE WORK)	4.0	16.80
10 55 50 43 19 70	R + R CHARGE AIR COOLER (INTAKE PIPE REMOVED)	2.0	8.40
50 38 09 50	DETACH + REFIT FRONT LOCK CARRIER (SERVICE POSITION) (BUMPER COVER REMOVED)	7.0	29.40
66 05 19 00	R + R RADIATOR GRILLE	2.0	8.40
63 29 19 50	R + R FRONT BUMPER COVER (RADIATOR GRILLE REMOVED)	4.0	16.80
63 29 55 90	RENEW FRONT BUMPER COVER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	9.0	37.80
66 04 55 83	RENEW FRT CTR VENTILATION GRILLE (REM)	1.0	4.20
66 44 19 50	R + R COWL TRIM (WIPER ARMS REMOVED)	2.0	8.40
92 25 20 00	R + R WIPER ARMS	3.0	12.60
92 60 19 50	R + R WASHER RESERVOIR (BUMPER COVER REMOVED)	2.0	8.40

Audatex System Using Manufacturer Times

Page 2 of 6

ode	Description	WU	Price SGD
92 60 55 50	RENEW WASHER RESERVOIR (REMOVED)	2.0	8.40
	INCLUDES: CONVERT ATTACHED PARTS		
10 83 19 00	R + R ENGINE COVER	2.0	8.40
17 50 19ZAX)	R + R OIL PAN	7.0	29.40
17 20 19 12)	R + R OIL PUMP	12.0	50.40
	(OIL PAN REMOVED)		
24 25 19 ZAX		3.0	12.60
17 50 55 50	RENEW OIL PAN (REMOVED)	1.0	4.20
19 20 19 70	R + R COOLING BLOWER HOUSING	4.0	16.80
19 70 19 70)	R + R RADIATOR	4.0	16.80
	(BUMPER COVER REMOVED)		
	INCLUDES: DETACH + REFIT LOCK CARRIER,		
	DRAIN + REFILL COOLANT		
19 70 55 50	RENEW RADIATOR (REMOVED)	3.0	12.60
	INCLUDES: CONVERT ATTACHED PARTS		
NO NUMBER	R + R LEFT GEARBOX SUPPORT	4.0	16.80
34 41 19 50	R + R PENDULUM SUPPORT	2.0	8.40
14,30 19 20)	R + R REAR ENGINE SUPPORT	3.0	12.60
01 19 20	R + R EXHAUST SYSTEM	13.0	54.60
	INCLUDES: R + R EXHAUST PIPES AND		
	SILENCER		
48 35 19 04)	R + R STEERING GEAR	9.0	37.80
	(WHEELS, OSCILLATION DAMPER AND NOISE		
	CONTROL PAN REMOVED)		
	INCLUDES: DETACH + REFIT ASSEMBLY		
	CARRIER		
	DOES NOT INCLUDE: ALIGN FRONT AND REAR,		
	READ OUT FAULT MEMORY	and the second s	eran com decree a substitute as
48 35 55 54	RENEW STEERING GEAR (REMOVED)	3.0	Charles and the second of the same of the second of the se
40 07 19ZAX)	R + R ASSEMBLY CARRIER	13.0	54.60
C C C C C C C C C C C C C C C C C C C	(NOISE CONTROL PAN, SUPPORT AND WHEELS		
	REMOVED)		
	INCLUDES: DETACH + REFIT STEERING GEAR		
	AND STABILIZER		
	DOES NOT INCLUDE: ALIGN FRONT AND REAR	**************************************	
44 05 19 00	R + R FRONT WHEEL (WHEELS)	2.0	And the second s
40 85 20 00)	R + R FRONT SPRING STRUTS	12.0	50.40
	(WHEELS REMOVED)		The state of the s
	DOES NOT INCLUDE: ALIGN FRONT AND REAR		
40 90 20 50	R + R BOTH FRONT SHOCK ABSORBERS	3.	12.60
	(STRUTS REMOVED)		
	INCLUDES: R + R STRUT BEARINGS AND		
	SPINGS		74 40
40 50 20 00)	R + R FRONT WHEEL BEARING HOUSINGS	17.	0 71.40
40 30 == ,	(WHEELS REMOVED)		
	INCLUDES: R + R SPEED SENSORS AND BRAKE		
	DISCS,		
	DETACH + REFIT DRIVE SHAFTS		
	DOES NOT INCLUDE: ALIGN FRONT AND REAR	essa Variation	0
40 07 55 50	RENEW AGGREGATE CARRIER (REMOVED)	1.	
40 41 20 00)	R + R BOTH FRONT DRIVE SHAFTS	4.	
40 50 56 50	RENEW BOTH FRONT WHEEL BEARING HOUSINGS	5	0 21.00
40 30 30 30	(BOTH WHEEL BEARING HOUSINGS REMOVED)		
	INCLUDES: R + R WHEEL BEARINGS AND WHEEL		

Audatex System Using Manufacturer Times

Page 3 of 6

ode	Description				wu	Price SGD	
1	· ·						
44 05 19 00	HUBS R + R REAR WHEEL (WHEEL	S)			2.0		
42 05 19 00)	R + R REAR AXLE BODY				2.0 17.0	8.40 71.40	
	(WHEELS REMOVED)				-7.0	71.70	
	INCLUDES: R + R COIL SPR						
	DETACH + REFIT BRAKE PIP						
	CABLES, BRAKE CALIPERS A	ND SHOCK					
	ABSORBERS DOES NOT INCLUDE: ALIGN	EDONT AND DEAD					
	BLEED BRAKE SYSTEM	TRUNT AND REAR,					
42 05 55 50	RENEW REAR AXLE MEMBER	e series as a contraction of the	CONTRACTOR SOME AND S		9.0	37.80	
	(REMOVED)						
	INCLUDES: CONVERT ATTAC	CHED PARTS					
47 01 07 50	BLEED BRAKE SYSTEM				3.0	12.60	
01 50 00 00	GFS / GUIDED FUNCTION (READ AND DELETE ERROR	MEMORY			2.0	8.40	
	AFTER REPAIR)	MEMORY					
44 95 03 00	ALIGN FRONT AND REAR VE	HICLE			9.0	37.80	
7	INCLUDES: CHECK TOE AND						
	R + R BRACKET AND ALIGN						
	DOES NOT INCLUDE: ADJUS	STMENT					
	Labour Cost			Hrs	WU		
	Panel / Mechanical Labor	uř		19.80	198.0	831.60	
	Alignment						
	Measuring Work			0.90	9.0	37.80	
	Total of Labour					869.40	
Paint							
Paint Work				Tin	ne Basis	10 WU/h	ē.
Code	Description - MF				wu	Price SGD)
Couc							
63 29 61 50	FRONT BUMPER NEW PART	PAINTING S1			9.0	37.80	
51 01 71 63)	PAINTING PREPARATION W		AL, PLASTIC NEW		11.0	46.20)
	PARTS S1 AND S2 (PART/S PREPARATION FOR PAINT (REMOVED)	ITH DADT(S)		2.0	8.40	
51 01 71 93	REMOVED) (ASSEMBLY OP		IIII FAKI(3)		2.0	0.40	,
	KEMOVED) (ASSEMBLE S.						
				Hrs	WU	Price SGD	
	Total Paint			2.20	22.0	92.40)
Spare Part	S	4		price	c ac at '	2015-06-01	7
	Description	Part Number	Part Source	price	s as at a	Price SGD	
Code	Description	Ture manipor					
0203	FRONT BUMPER	5K0 807 221 AD	Original			900.00	1 1
0283		GRU				PA 500 55	
0296	FRT CTR COWL GRILLE	5K0 853 671 J 04				600.00 350.00	ノグレ
0393	FRT SPOILER BRACKET	5K0 805 915 B	Original			کہ 350.00	, 1
	ENGINE MOUNTING	9B9 1K0 802 068	Original			180.00	7
1299	FIAGUAL MODIALING	11/0 002 000	J. Igiliai				

Page 4 of 6

Audatex System Using Manufacturer Times

Code	Description	Part Number	Part Source	Price SGD
1436	FLUID RESERVOIR	1K0 955 453 S	Original	2 180.00 X
1437	WASHER PUMP	1K6 955 651	Original	
7009	L/ASSY CARRIER CONS	1K0 199 295 E	Original	
7010	R/ASSY CARRIER CONS	1K0 199 296 J	Original	€ 280.00 ×
7011	ASSEMBLY CARRIER	1K0 199 313 AL	Original	280.00 7
7035	L/DRIVE SHAFT CPL	3C0 407 271 AJ	Original	By 900.00 -
7036	R/DRIVE SHAFT CPL	3C0 407 272 BD	Original	N 1,350.00 X
7047	L/F TRACK CONT ARM	1K0 407 151 AC	Original	7 1,400.00 X
7048	R/F TRACK CONT ARM	1K0 407 152 AC	Original	ル 260.00 x 260.00 X
7061	L/F GUIDE JOINT	1K0 407 365 C	Original	
7062	R/F GUIDE JOINT	1K0 407 366 C	Original	CONTRACTOR AND ADDRESS OF THE PARTY OF THE P
7081	L/WHEEL BEARING HSG	1KO 407 255 AA	Original	
7082	R/WHEEL BEARING HSG	1KO 407 256 AA	Original	~~ 480.00 ₹
7087	L/FR SHOCK ABSORBER	1TO 413 031 1F	Original	480.00 X
7088	R/FR SHOCK ABSORBER	1TO 413 031 JE	Original	ル 750.00 X ル 750.00 x
7095	L/F S-ABSORB BRACKET	1K0 413 031 3L	Original	
7096	R/F S-ABSORB BRACKET		Original	14 90.00 X
7131	L/F WHEEL HUB/BRG	5K0 498 621		회사의 맛이 얼마가게 맛있는 것 같아. 그는 나는 회사가 가득하는 후 프라프라트 다시 없다.
7132	R/F WHEEL HUB/BRG		Original	120.00 X 120.00 X
7361	FRONT STABILISER	5K0 498 621	Original	
. 7		1K0 411 303 AQ	Original	280.00 7
	L/ANTI-SQUAT ROD	5Q0 411 315 A	Original	رم 150.00 ×
7278	R/ANTI-SQUAT ROD	5Q0 411 315 A	Original	150.00 ^X
7300	POWER STEERING	1K2 423 055 K	Original	3,200.00 7
7309	L/TIE ROD	1K0 423 810 A	Original	△ 120.00 × 120.00 ×
7310	R/TIE ROD	1K0 423 810 A	Original	
7311	L/TIE ROD BALL JOINT	1K0 423 811 J	Original	الم 120.00 X
7312	R/TIE ROD BALL JOINT	1K0 423 812 J	Original	7 120.00 X R 400.00 —
7761	RADIATOR	1K0 121 251 AB	Original	0.00
7927	LWR CYL BLOCK FRAME	06B 103 307 C	O-i-iI	Bn 480.00 ~
8065	ENGINE SUMP	06F 103 601 J	Original	240.00 7
8622	RIGHT ENGINE SUPPORT		Original	200.00 7
8631	R/ENGINE MOUNTING	8J0 199 262	Original	180.00 7
8657	FRONT ENGINE SUPPOR		Original	€ 450.00 ×
8745	INTERCOOLER	3C0 145 805 AM	Original	CM 200.00
8771	ENGINE PROTECTION	1K0 825 235 AE	Original	
8795	FRT CTR EXHAUST PIPE	1K0 254 512 HX	Original	
8806	FRT EXH PIPE SEAL	1K0 253 115 AB	Original	Mc 40.00 —
8809	FRONT LAMBDA PROBE	06J 906 262 AA	Original	380.00 7 By 2.850.00 —
8833	CENTRE REAR EXHAUST	5K6 253 181 AN	Original	
#1	FRT EXHAUST CLAMP	1K0 253 141 H	Original	120.00 7
8843	FRT EXH PIPE BRACKET	1K0 253 144 BD	Original	380.00 7
9081	REAR SUPPORT FRAME	1K0 505 315 BM	Original	900.00 7
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			27,680.00
u: Used parts	Total			27,680.00

	Vtrac

	Code	Description	Price SGD
1000 ENGINE ECU REPROGRAM ENGINE ECU 500.00* 7 Total Extras	-		The state of the s

Audatex System Using Manufacturer Times

Page 5 of 6

Final Calculation

	SGD	SGD
Parts Total Parts	27,680.00	27,680.00
Labour Time Base 10 WU/h		
Total 198.0 WU X 42.00 SGD/h Alignment	831.60	
Measuring Work	37.80	
Total of Labour		869.40
Total Of Extras		500.00
Paint Work Time Base 10 WU/h		
Labour Cost 22.0 WU X 42.00 SGD/h	92.40	
Total Paint Including Material		92.40
Repair Cost Excludes GST		29,141.80
GST (+7.0%)		2,039.93
Repair Cost Included GST		31,181.73

Comments * - USER SUPPLIED DATA	LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting
NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS	 To display damaged part(s) during resurvey Parts prices are subject to confirmation
Assessment Note	 Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
No assessment notes entered.	 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
	Acknowledged by Repairer
	Signature:
	Date:



IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 26/10/2021 12:23 (SGT)

Date of Accident 24/10/2021 18:20 (SGT) **Exact Location of Accident**

SLE, Singapore

Additional Location Information SLE TOWARDS CHANGI AFTER THE BENDS JOINING FROM

.BKE

Private use

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMT3804T

INSURED/POLICYHOLDER

Is company? No

Name Of Registered Owner LOH ZHI WEI NRIC No SXXXX513Z

Email Address mito_of_cagiva@hotmail.com

Mobile Phone No (Phone) +65-91995099 Alternative Phone No (Office) +65-91995099

VEHICLE PARTICULARS

Volkswagen ufacturer

Golf Model

Variant

Exact purpose for which vehicle was being used at time of

accident Are you claiming under your own insurance policy for repair to

Yes your vehicle? Private car

Vehicle Category Auto Transmission

1984 CC

INSURANCE COMPANY

China Taiping Insurance (Singapore) Pte. Ltd. Name of Insurance Company

Type of Coverage Comprehensive No

Fleet Policy

DMPCSNW00079542100 Policy Number

Cover Note Number

DRIVER

LOH ZHI WEI Name of Driver

Accident report SD0821AQ0001

Page 1 of 15



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 26/10/2021 12:23 (SGT) Date of Accident 24/10/2021 18:20 (SGT)

Exact Location of Accident SLE, Singapore

Additional Location Information SLE TOWARDS CHANGI AFTER THE BENDS JOINING FROM

.BKE

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMT3804T

INSURED/POLICYHOLDER

Is company? No

LOH ZHI WEI Name Of Registered Owner NRIC No SXXXX513Z

mito_of_cagiva@hotmail.com **Email Address** (Phone) +65-91995099 Mobile Phone No

Alternative Phone No (Office) +65-91995099

VEHICLE PARTICULARS

ufacturer Volkswagen Golf Model

Variant

Exact purpose for which vehicle was being used at time of Private use

accident Are you claiming under your own insurance policy for repair to

Yes your vehicle? Private car Vehicle Category

Auto Transmission

1984 CC

INSURANCE COMPANY

China Taiping Insurance (Singapore) Pte. Ltd. Name of Insurance Company

Comprehensive Type of Coverage No

Fleet Policy DMPCSNW00079542100 Policy Number

Cover Note Number

DRIVER

LOH ZHI WEI Name of Driver

Accident report SD0821AQ0001

Page 1 of 15

Vehicle Owner Particulars Owner ID Type: Singapore NRIC Owner ID: 513Z Vehicle Details Vehicle No.: SMT3804T Vehicle to be Exported: Yes Intended Deregistration Date: 01 Nov 2021 Vehicle Make: **VOLKSWAGEN** Vehicle Model: GOLF R 2.0L 5DR 5K1RX7 Primary Colour: Grey Manufacturing Year: 2010 CDL041426 Engine No.: WVWZZZ1KZBW130290 Chassis No.: 188.0 kW (252 bhp) Maximum Power Output: \$37,833.00 Open Market Value: 14 Jan 2011 Original Registration Date: 14 Jan 2011 First Registration Date: 4 Transfer Count: \$37,833.00 Actual ARF Paid: **Intended PARF Rebate Details** Forfeited PARF Eligibility: PARF Eligibility Expiry Date: \$0.00 PARF Rebate Amount: Intended COE Rebate Details 31 Aug 2030 COE Expiry Date: B - Car (1601cc & above) COE Category: 10 COE Period(Years): \$32,914.00 \$29,065.00 PQP Paid: COE Rebate Amount: \$29,065.00 Total Rebate Amount: The information contained herein is correct as at 25 Oct 2021

Enquire PARF/COE Rebate for Registered Vehicle

OK