



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7170X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT DOOR RH	DEFORMED	1,797.20	1,797.20
1	FRT DOOR GEAR/REGULATOR RH	SERVICEABLE	750.40	-
1	FRT DOOR INNER LOCK RH	SERVICEABLE	385.60	-
1	FRT DOOR KEY LOCK SET RH	DENTED	353.50	353.50
1	FRT DOOR OUTER HANDLE RH	DISTORTED	234.80	234.80
1	FRT DOOR POWER MOTOR RH	SERVICEABLE	689.20	-
1	FRT DOOR PROTECTOR RH	NECESSARY	186.20	186.20
1	FRT DOOR GLASS RH	CRACKED	215.20	215.20
	LESS 20% DISCOUNT		-922.42	-557.38
			3,689.68	2,229.52
	<u>SPECIAL NETT ITEMS</u>			
1	FRT DOOR COMFORTDELGRO LOGO STICKER RH (SN)	NECESSARY	75.00	75.00
			75.00	75.00
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TRANSFER OF DOOR.		120.00	120.00
	CHECK WIRING.		60.00	20.00
			1,180.00	740.00
	GRAND TOTAL		4,944.68	3,044.52
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			3,044.52

Report Ref No. NS/INC21011065/Vvcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.