



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3587T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR DOOR LH	DEFORMED	1,789.90	1,789.90
1	REAR DOOR OUTER MOULDING	SCRATCHED	125.30	125.30
	LESS 20% DISCOUNT		-736.70	-383.04
			2,946.80	1,532.16
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR COMFORTDELGRO & APPS STICKER RH (SN)	NECESSARY	80.00	80.00
			80.00	80.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		1,050.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	TUFF KOTE.		60.00	30.00
	TRANSFER OF DOOR.		120.00	120.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	50.00
			1,980.00	1,400.00
GRAND TOTAL			5,006.80	3,012.16
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,012.16

Report Ref No. NS/INC21011066/Vqcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.