

Our Job Ref No 305491252

Date 28/10/2021

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508909
Fax: 6546 8156


FINALIZATION FORM

To : LKK
Attn : THEVAN
SH 8909J

Fax : _____
DOA: 17/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SMW2938G
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$11,200.00
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 6 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : THEVAN
Date : 29/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

PANEL BEATING		\$1,200.00	1050
SPRAY PAINT		750	900.00
REMOVE/REFIX REVERSE SENSOR		\$80.00	30
CHECK WIRING		\$50.00	20
TUFF KOTE		\$50.00	20
TOWING		\$60.00	✓
REMOVE/REFIX REAR UNDERCARRIAGE		\$150.00	✓
ADJUST FOUR WHEEL ALIGN		\$100.00	✓ 60
REMOVE/REFIX REAR WINDSCREEN GLASS		\$120.00	✓
ADVERTISEMENT LOGO - BOOTLID		\$100.00	✓ nec
ADVERTISEMENT LOGO - FENDER		\$200.00	✓ nec
DIAGNOSTIC & RESETTING FAULT CODE		\$150.00	50
TOTAL LABOUR		\$3,860.00	✓
ESTIMATE TOTAL		\$15,321.45	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Truman@LKKauto.com
 82235769
 18/10/21 1800
 LIS after repair photo
 60 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

VEHICLE NO SH8909J
 MAKE HYUNDAI
 MODEL IONIQ

DATE: 18/10/2021
 MVA JUMANI
 DOA: 17. Oct. 2021

NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$459.40 / cut
1	REAR BUMPER CENTRE MLDG			\$451.25 / scr
1	REAR BUMPER BEAM			\$394.80 ?
1	REAR BUMPER REFLECTOR RH			\$41.45 / crg
10	REAR BUMPER CLIPS			\$22.00 / nec
1	REAR BUMPER BEAM BRACKET RH			\$138.10 ?
1	REAR BUMPER SIDE COVER RH			\$108.00 / nec
1	REAR BUMPER SIDE BRACKET RH			\$55.80 / nec
1	REAR FENDERRH			\$1,768.30 / net
1	REAR FENDER AIR DUCT RH			\$87.30 / mis
1	CRU RADER SENSOR RH			\$2,910.90 ?
1	BOOTLID EMBLEM - IONIQ			\$31.30 / nec
1	BOOTLID EMBLEM - HYBRID			\$24.30 / nec
1	BOOTLID EMBLEM - H			\$28.00 / nec
1	BOOTLID COVER			\$2,480.40 / net
1	WHEEL RIM CAP			\$346.40 / scr
1	REAR TRAILING RH			\$265.40 ?
1	REAR ASSIST RH			\$227.90 ?
1	REAR S/ABSORBER RH			\$230.50 ?
1	REAR S/ABSORBER MTG RH			\$133.10 ?
1	REAR UPPER ARM RH			\$239.50 ?
1	REAR LOWER ARM RH			\$393.10 ?
1	REAR KNUNCKLE ARM RH			\$538.10 ?
1	FRT BUMPER ASSY			\$430.90 / cut
10	FRT BUMPER CLIPS			\$22.00 / nec
1	HEADLAMP ASSY RH			\$1,993.65 / crg
1	FRT BUMPER BRACKET RH			\$35.00 / nec
	<i>Supp Towbar Outer RH</i>			\$870.40
		1313505		
		262601		
		10504.04		
	SUB TOTAL			\$13,856.85
	LESS 20%			\$2,771.37
	DISCOUNTED TOTAL			\$11,085.45
	BOOTLID COMFORT LOGO			\$30.00 NET/nh
	BOOTLID COMFORT TEL.NOS LOGO			\$30.00 NET/nh
	BOOTLID APPS LOGO			\$40.00 NET/nh
	REVERSE SENSOR			\$180.00 NET/cc
	WINDSCREEN SEALANT	326		\$46.00 NET/nh
	REAR NUMBER PLATE	3260		\$50.00 NET/nh
				\$376.00
	Labour Charge	29340		
	PANFI REATING - FRT			\$400.00 350

REMOVE/REFIX REVERSE SENSOR	\$80.00	30
CHECK WIRING	\$50.00	20
TUFF KOTE	\$50.00	20
TOWING	\$60.00	✓
REMOVE/REFIX REAR UNDERCARRIAGE	\$150.00	✓
ADJUST FOUR WHEEL ALIGN	\$100.00	✓/60
REMOVE/REFIX REAR WINDSCREEN GLASS	\$120.00	✓
ADVERTISEMENT LOGO - BOOTLID	\$100.00	✓/nec
ADVERTISEMENT LOGO - FENDER	\$200.00	✓/nec
DIAGNOSTIC & RESETTING FAULT CODE	\$150.00	50
TOTAL LABOUR	\$3,860.00	3211
ESTIMATE TOTAL	\$15,321.45	—

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan@Lkhauto.com

82235769

18/10/21 1800

L/S after repair photo

5 days wp

1400744

2801-48

11705-96