

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011072/KUY3N2**Date:** 25/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00004652100		
Claimant Vehicle No :	SMM6925U	Insured Vehicle No :	PA9878E		
Date of Loss:	27/10/2021	Nature of Claim:	TP	Claim No:	SNM21D206171/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM6925U		
Make & Model:	HONDA VEZEL, 1.5 X A (A)	Engine No:	LEB5926307
Reg. Date:	10/07/2019 (Man. Year: 2016)	Chassis No:	RU31226295
Colour:	Metallic Bronze	Odometer:	132109 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,550.44	1,142.04	2,408.40	67.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,320.00	930.00	41.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,800.44	2,462.04	3,338.40	57.55
Approved Total (Overridden) (\$\$)		1,950.00		
(\$\$)	5,800.44	1,950.00	3,850.44	66.38
+ GST 7.00/7.00% (\$\$)	406.03	136.50	269.53	66.38
Nett Amount (\$\$)	6,206.47	2,086.50	4,119.97	66.38

INSPECTION

Date of Assignment:	29/10/2021	
Date Inspected:	29/10/2021 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X A (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM6925U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Serviceable	1,865.70 FL	*- FL
2	1		*FRONT HEADLAMP LOWER BRACKET RH	Serviceable	34.20 FL	*- FL
3	1		*FRONT BUMPER	Repair	898.30 FL	*- FL
4	1		*FRONT BUMPER SIDE BRACKET RH	Distorted	23.90 FL	*23.90 FL
5	1		*FRONT FENDER RH	Bent	421.10 FL	*421.10 FL
6	1		*FRONT FENDER INNER SHIELD RH	Serviceable	112.30 FL	*- FL
7	1		*FRONT FENDER WHEEL ARCH RH	Bent	163.80 FL	*163.80 FL
8	1		*SIDE MIRROR ASSY RH	Dented/Cracked	712.50 FL	*712.50 FL
9	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Not Necessary	80.00 FS	*- FS
11	1		*FRONT FENDER INNER SHIELD CLIPS RH	Necessary	50.00 FS	*50.00 FS
12	1		*FRONT FENDER WHEEL ARCH CLIPS RH	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,396.80	1,406.30
- List Item Discount on L Items 20.00/20.00% (S\$)	846.36	264.26
Total Parts (S\$)	3,550.44	1,142.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST ACCIDENT AREA	New	1,000.00	550.00
2	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREA	New	800.00	720.00
3	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	200.00	30.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	100.00	20.00
Gross Labour Cost (\$)			2,250.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >