Our Job Ref No 305491473 Date 23/10/21				COMFORTDELG				
FINA	LIZATI	ON FORM		The same of the sa		Comm	ontbellom Engineering Pie Ling lyding Chive Singapore soeago	
To			LKK	,		EAv. 6	154d 8158	
Attn	M	ī				Fax		
Vehic	de Reg	No.	SH 9647H					
The s	SUIVEV	and onti-		CTPL			20/10/2021	
	_	and estimi	ates of the repair	rs of the above-me	ntioned vehicle	are as follows	10/6061	
1.	Their	epair job s	shall bill to:		NTUC			
2	The finalized amount shall be:				***	GBK1615M		
	(a)		arts after List dis	count				
	(p)	Labour (	Charges					
		Total for	r Part-By-Part R	Repair Cost				
	(c.)						\$0.00	
	(0.)	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less:						
		Final Lu	impsum Repair	cost aπer Less:	20%	-,		
							\$2,000.00	
3.	Estim	natod						
	23011	rated nom	nal period for rep	pairs:	3 wo	rking days.		
4.	We s work	hall treat ing days	the above amo	unt as Correct an	d Confirmed if	there is no re <sub>l</sub>	oly from you within 7	
				unt as Correct an	d Confirmed if	there is no re <sub>l</sub>	ply from you within 7	
			the above amo	unt as Correct an	d Confirmed if	there is no rep		
				unt as Correct an	d Confirmed if	there is no re <sub>l</sub>		
	Than	k you for y		unt as Correct an	d Confirmed if	there is no rep		
	Than	k you for y	your assistance.	unt as Correct an	d Confirmed if We fin	there is no repector of the ending the end amount of the end of th	stimates and	
	Than Signa Name	k you for y ature : But the second in the se	your assistance.	unt as Correct an	d Confirmed if  We fin  Sig	there is no repectation of the earling amount grature :	stimates and	
	Signa Name Tel	k you for y ature: e: M3 : 62	S. LOKE YY	unt as Correct an	d Confirmed if We fin	there is no repectation of the earling amount grature :	stimates and	
5.	Signa Name Tel Fax	ature:e : 62	S. LOKE YY 2148355 5468156	unt as Correct an	d Confirmed if  We fin  Sig	there is no repectation of the earling amount grature :	stimates and	
5.	Signa Name Tel Fax	k you for y ature: e: M3 : 62	S. LOKE YY 2148355 5468156	unt as Correct an	d Confirmed if  We fin  Sig	there is no repectation of the earling amount grature :	stimates and	
5.	Signa Name Tel Fax  Official	ature:e : 62	S. LOKE YY 2148355 5468156	Amount	d Confirmed if  We fin  Sig  Na  Da  Document  Attached	there is no repectation of the earling amount grature :	stimates and	
5.	Signa Name Tel Fax	ature :e : 62 : 65	S. LOKE YY 2148355 5468156	À	d Confirmed if  We fin  Sig  Na  Da  Document Attached Yes or No	confirm the ealized amount  gnature: me: te: Confirm By	Thuan 2 9/10/2/	
. Re	Signa Name Tel Fax  Difficial	ature :e : 62 : 65 Use Only	S. LOKE YY 2148355 5468156	À	d Confirmed if  We fin  Sig  Na  Da  Document  Attached  Yes or No  YES	confirm the ealized amount  gnature: me: te: Confirm By	Thuan 2 9/10/2/	
. Re	Signa Name Tel Fax  Dfficial	ature : e : Ms : 62 : 65  Use Only  Item  ate P/Day ncome Pai	S. LOKE YY 2148355 5468156	À	d Confirmed if  We fin  Sig  Na  Da  Document Attached Yes or No	confirm the ealized amount  gnature: me: te: Confirm By	Thuan 2 9/10/2/	
. Re	Signa Name Tel Fax  Difficial ental Rass of Intervey For A Sear	ature : e : Ms : 62 : 65  Use Only Item ate P/Day ncome Paiees rch Fee	S. LOKE YY 2148355 5468156	À	d Confirmed if  We fin  Sig  Na  Da  Document  Attached  Yes or No  YES	confirm the ealized amount  gnature: me: te: Confirm By	Thuan 2 9/10/2/	
. Re	Signa Name Tel Fax  Difficial ental Rass of Intervey For A Seare	ature : e : Ms : 62 : 65  Use Only  Item  ate P/Day ncome Pai	S. LOKE YY 2148355 5468156	Amount	d Confirmed if  We fin  Sig  Na  Da  Document  Attached  Yes or No  YES	confirm the ealized amount  gnature: me: te: Confirm By	Thuan 2 9/10/2/	

## COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH 9647H

Make

:HYUNDAI

Model

: IONIQ(GI)

Date: 20/10/2021

Insurance: NTUC

MVA: MS, LOKE YY

			MATALINO, ESINE 11			
Qty	Parts Description / Labour	Туре	Unit Price	Amount		
	1 FRT BUMPER COVER			\$430.90		
10	FRT BUMPER CLIPS			\$22.00		
	1 FRT BUMPER SIDE BRACKER RH			\$28.00		
	1 HEADLAMP RH			\$1,993.65		
	1 DAY LIGHT RH			\$642.50		
,	1 FRT BUMPER SIDE MOULDING RH			\$186.90		
	1 FRT FENDER RH			\$588.80		
	1 EMBLEM – BLUE DRIVE RH			\$26.60		
	1 FRT WHEEL HUB CAP RH			\$346.40		
	SUB TO	TAL		\$4,265.75		
	LESS	20%		\$853.15		
	DISCOUNTED TO	TAL		\$3,412.60		
	FRT FENDER ADVERTISEMENT LOGO LH			\$100.00 <b>\$100.00</b>		
	Labour Charge					
	PANEL BEATING			\$1,050.00		
	SPRAY PAINTING CHARGE			\$600.00		
	TUFF KOTE			\$60.00		
	CHECK ALL LIGHTING			\$60.00		
	TOTAL LAB	OUR		\$1,770.00		
	ESTIMATE TO	TAL		\$5,282.60		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theremal thauto.10m
82235769
20/10/21 1630
(15 after repair photo
3 clays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Dale: