

◀	<	1 of 2 ?	>	▶	↺	↻	100% ▼	📄	🖨	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref: CS/SMO21011075/Uvf3		
50 RAFFLES PLACE #03-03		Date: 29/10/2021		
SINGAPORE LAND TOWERS SINGAPORE 048623		Code: SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJU 5334A	Veh. Inspected	SJM 9108C	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103210/RUC	Excess (\$)	0.00	
Assign From	MELVIN YE YONG KANG	Assign Date	29/10/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/10/2021	Inspection Date	29/10/2021	
Survey held at	TK MOTOR WORKSHOP 1 KAKI BUKIT AVENUE 6, #02-56, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				