



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref: CS/TP21011080/Uuf3e2	
BLK 1 KAKI BUKIT AVE 6			Date: 08/11/2021	
#01-28/53/55/56 (MAIN OFFICE)SINGAPORE 417883				
ON BEHALF OF CHEW BENG LEE			Code: TP149	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.		Veh. Inspected		SML 9371C
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		29/10/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA RAV4 (A)	c.c	1987	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTMY43FV80D503117	Colour	GREY	
Odometer	57180 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	BRIDGESTONE	8 mm	
L/H Front Tyre	225/60 R18	BRIDGESTONE	8 mm	
R/H Rear Tyre	225/60 R18	BRIDGESTONE	8 mm	
L/H Rear Tyre	225/60 R18	BRIDGESTONE	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/10/2021	Inspection Date	29/10/2021	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	