

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE PTE LTD		Re	ef:	CS3/ASM21011082/T1ty3e2
	8 SHENTON WAY SINGAPORE 0688	Da	ate:	02/12/2021	
	ATTN: NG STACE	Y	Co	ode:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 5002X	Veh. Inspected		FBB 8922C
	Policy No.	VFX/P2413997	Coverage (\$)		0.00
	Claim No.	S1M03KBR	Excess (\$)		0.00
	Assign From	NG STACEY	Assign Date		29/10/2021
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA CB400	c.c		399
	Engine No.	HIDDEN	Year of Reg.		2007
	Chassis No.	JH2NC39966M200857	Colour		WHITE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	120/60 R17	METZELER		5 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	160/60 R17	METZELER		5 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.				
5.	General Information				
	Accident Date	19/10/2021	Inspect Date / Tin	ne	01/11/2021 (04:30 PM)
	Survey held at	AHM PERFORMANCE			
	BLK 1 KAKI BUKIT AVE 6 #02-46 SINGAPORE 417883				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$5,000				
5b.	b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/ASM21011082/T1ty3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.