

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
 (Singapore) Pte Ltd
 3 Anson Road
 #15-00 Springleaf Tower
 Singapore 079909

Claim Details

Case Ref. No. : TP/102021/5043
Date : 29-10-2021
Accident Date : 28-10-2021

Vehicle Details

Make & Model : Toyota NOAH HYBRID 1.8X CVT
Chassis No : ZWR800309771
Registration No : SMH2028L

Third Party Vehicle Details

Registration No : GBG9729L

S/N	Description	Qty	Amount (\$)
1	REAR TAILGATE / <i>Part</i>	1.00	\$1,812.00 ✓
2	REAR TAILGATE GLASS / <i>Sm</i>	1.00	\$1,297.80 ✓
3	REAR TAILGATE GLASS MOULDING / <i>acc</i>	1.00	\$164.70 135
4	REAR TAILGATE EMBLEM / <i>acc</i>	1.00	\$66.78 ✓
5	REAR TAILGATE OUTER CHROME MOULDING / <i>CRA</i>	1.00	\$907.80 581
6	REAR TAILGATE "HYBRID SYNERGY DRIVE" EMBLEM / <i>acc</i>	1.00	\$57.90 49.8
7	REAR TAILGATE NO. PLATE LIGHT / <i>CRA</i>	1.00	\$91.90 ✓
8	REAR TAILGATE THIRD BRAKE LIGHT / <i>CRA</i>	1.00	\$195.70 ✓
9	REAR TAILGATE WIPER MOTOR / <i>NN</i>	1.00	\$827.40
10	REAR TAILGATE WIPER ARM / <i>acc</i>	1.00	\$67.50
11	REAR TAILGATE WIPER BLADE / <i>acc</i>	1.00	\$35.10
12	REAR TAILGATE INNER TRIMBOARD / <i>acc</i>	1.00	\$673.00 605.1
13	REAR TAILGATE TRIM COVER - TOP / <i>CRA</i>	1.00	\$231.40 204.5
14	REAR TAILGATE TRIM COVER - RH / <i>acc</i>	1.00	\$28.50 ✓
15	REAR TAILGATE PULL HANDLE COVER / <i>NN</i>	1.00	\$33.50
16	REAR TAILGATE INNER LOCK / <i>BT</i>	1.00	\$467.00 ✓
17	REAR TAILGATE RUBBER / <i>mi</i>	1.00	\$372.30 ✓
18	REAR RH TAILLAMP / <i>CRA</i>	1.00	\$732.60 ✓
19	REAR LH TAILLAMP / <i>CRA</i>	1.00	\$732.60 ✓
20	REAR RH CORNER COVER / <i>NN</i>	1.00	\$229.60
21	REAR LH CORNER COVER / <i>acc</i>	1.00	\$229.60 ✓
22	REAR RH CORNER COVER RETAINER / <i>NN</i>	1.00	\$160.70
23	REAR LH CORNER COVER RETAINER / <i>acc</i>	1.00	\$160.70 75.6
24	REAR BUMPER / <i>acc</i>	1.00	\$750.90 ✓
25	REAR BUMPER RH REFLECTOR / <i>NN</i>	1.00	\$82.30
26	REAR BUMPER LH REFLECTOR / <i>Car</i>	1.00	\$82.30 ✓
27	REAR BUMPER RH SIDE RETAINER / <i>NN</i>	1.00	\$159.90
28	REAR BUMPER LH SIDE RETAINER / <i>acc</i>	1.00	\$159.90 120
29	REAR END PANEL / <i>acc</i>	1.00	\$735.70 ✓
30	REAR END PANEL TOP TRIM / <i>acc</i>	1.00	\$233.10 204.5

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No: 199906067G

31	REAR SPARE TYRE PANEL <i>x 1/2 price</i>	1.00	\$781.70
32	REAR SPARE TYRE PANEL TOP COVER <i>- BT</i>	1.00	\$1,105.50 845
33	REAR SPARE TYRE PANEL INSULATOR <i>- TN</i>	1.00	\$455.20 427.7
34	REAR TOOL BOX <i>✓ TN</i>	1.00	\$491.60 ✓
35	REAR RH FENDER INNER TRIMBOARD <i>= 500</i>	1.00	\$741.80 612
36	REAR LH FENDER INNER TRIMBOARD	1.00	\$741.80 612
37	REAR FENDER INNER TRIMBOARD CLIPS @ \$3.50 <i>/ M6C</i>	20.00	\$70.00 30

\$16,167.78 12589.48

Discount: -25%

(\$4,041.95) 9442.11

\$12,125.83

38	REAR TAILGATE REVERSE CAMERA <i>- 4PM</i>	1.00	\$380.00 250
39	REAR BUMPER PARKING SENSOR <i>- 4PM</i>	1.00	\$280.00 200
40	REAR WINDSCREEN GLASS GUM <i>- M6C</i>	1.00	\$60.00 ✓
41	REAR NO. PLATE <i>- M6C</i>	1.00	\$40.00 ✓
42	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$150.00 120
43	TO REMOVE AND REFIX REAR UNDERCARRIAGE	1.00	\$280.00 XAVN
44	TO REPAIR DAMAGES	1.00	\$1,600.00 1200
45	TO SPRAY PAINTING	1.00	\$1,300.00 1200

3070

Subtotal w/o GST: \$16,215.83

12512.11

543.35

Total: 13055.46

*10 Days.
 P/P
 before paint photos.
 Gino Riop
 28/10/21*

LMK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental claims must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.