



**Estimated Cost of Repair  
 (Supplementary)**

**Attention To** : **China Taiping Insurance  
 (Singapore) Pte Ltd**  
 3 Anson Road  
 #15-00 Springleaf Tower  
 Singapore 079909

**Claim Details**

**Case Ref. No.** : TP/102021/5043  
**Date** : 29-10-2021  
**Accident Date** : 28-10-2021

**Vehicle Details**

**Make & Model** : Toyota NOAH HYBRID 1.8X CVT  
**Chassis No** : ZWR800309771  
**Registration No** : SMH2028L

**Third Party Vehicle Details**

**Registration No** : GBG9729L

S/N	Description	Qty	Amount (S\$)
1	REAR KEYLESS SENSOR ✓ BR	1.00	\$117.10
2	REAR LH FENDER AIR VENT ✓ DE	1.00	\$135.87
3	REAR LH FENDER SIDE PROTECTOR ✓ BR	1.00	\$471.50
			\$724.47
<b>Discount: -25%</b>			(\$181.12)
			\$543.35
<b>Subtotal w/o GST:</b>			\$543.35

Issued by Raymond Teo

This is a computer-generated document. No signature is required.