


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD  TP /  S / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s VIN'S MOTOR  
 of \_\_\_\_\_  
 Insured: GBG 9729L  
 Policy No. DMCVSNW00123102003  
 Claims No. SNM21D206196/C02/TANCHC  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SMH2028L Yr Regn: 15 Jan/2019  
 Type  M.Car /  M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: TOYOTA NOAH HYBRID 1.8X c.c. 1797  
 Colour Black A/C: Insured / Std / NI / NA  
 Sp. Reading 25969 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: ZWR800309771  
 Gen. Cond  Good /  Fair /  Poor /  Burnt  
 Steering:  Inorder /  Jammed /  Leaked /  Burnt or  
 Brake:  Inorder /  Jammed /  Leaked /  Burnt or  
 Modi: Nil / S/Rim / STD A/R or \_\_\_\_\_

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \$109k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 10 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Tyre Size: F: 195/65R15  
 R: 195/65R15  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU  PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>28/10/2021</u>		D.O.I. <u>29-10-2021</u>	
Survey held at _____ W/S		3:30PM	

 Des. of Damages: Frt /  Rea /  O/S /  N/S /  U/C /  Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/8/22	Final fig \$13,055.46 (red 3703.72, 22%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) 10/8/22-typist  
 Report Subject: Merimen  
 Lump Sum / MPB: \$13,055.46

Days Of Repair: 10  
 Resurvey No. of Trip: 1  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Insp (\$ \_\_\_\_\_)  
 : Washend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	