

# Vin's

**Vin's Motor Pte Ltd**  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

## Estimated Cost of Repair

**Attention To :** China Taiping Insurance  
 (Singapore) Pte Ltd  
 3 Anson Road  
 #15-00 Springleaf Tower  
 Singapore 079909

### Claim Details

**Case Ref. No. :** TP/102021/5043  
**Date :** 29-10-2021  
**Accident Date :** 28-10-2021

### Vehicle Details

**Make & Model :** Toyota NOAH HYBRID 1.8X CVT  
**Chassis No :** ZWR800309771  
**Registration No :** SMH2028L

### Third Party Vehicle Details

**Registration No :** GBG9729L

S/N	Description	Qty	Amount (\$)
1	REAR TAILGATE / <i>Part</i>	1.00	\$1,812.00
2	REAR TAILGATE GLASS / <i>Sm</i>	1.00	\$1,297.80
3	REAR TAILGATE GLASS MOULDING / <i>acc</i>	1.00	\$164.70
4	REAR TAILGATE EMBLEM / <i>acc</i>	1.00	\$66.78
5	REAR TAILGATE OUTER CHROME MOULDING / <i>acc CRA</i>	1.00	\$907.80
6	REAR TAILGATE "HYBRID SYNERGY DRIVE" EMBLEM / <i>acc</i>	1.00	\$57.90
7	REAR TAILGATE NO. PLATE LIGHT / <i>?</i>	1.00	\$91.90
8	REAR TAILGATE THIRD BRAKE LIGHT / <i>acc CRA</i>	1.00	\$195.70
9	REAR TAILGATE WIPER MOTOR / <i>?</i>	1.00	\$827.40
10	REAR TAILGATE WIPER ARM / <i>x acc</i>	1.00	\$67.50
11	REAR TAILGATE WIPER BLADE / <i>x acc</i>	1.00	\$35.10
12	REAR TAILGATE INNER TRIMBOARD / <i>acc</i>	1.00	\$673.00
13	REAR TAILGATE TRIM COVER - TOP / <i>acc CRA</i>	1.00	\$231.40
14	REAR TAILGATE TRIM COVER - RH / <i>acc</i>	1.00	\$28.50
15	REAR TAILGATE PULL HANDLE COVER / <i>x acc</i>	1.00	\$33.50
16	REAR TAILGATE INNER LOCK / <i>BT</i>	1.00	\$467.00
17	REAR TAILGATE RUBBER / <i>mi</i>	1.00	\$372.30
18	REAR RH TAILLAMP / <i>acc CRA</i>	1.00	\$732.60
19	REAR LH TAILLAMP / <i>acc CRA</i>	1.00	\$732.60
20	REAR RH CORNER COVER / <i>x acc</i>	1.00	\$229.60
21	REAR LH CORNER COVER / <i>acc</i>	1.00	\$229.60
22	REAR RH CORNER COVER RETAINER / <i>x acc</i>	1.00	\$160.70
23	REAR LH CORNER COVER RETAINER / <i>acc</i>	1.00	\$160.70
24	REAR BUMPER / <i>acc</i>	1.00	\$750.90
25	REAR BUMPER RH REFLECTOR / <i>x acc</i>	1.00	\$82.30
26	REAR BUMPER LH REFLECTOR / <i>acc</i>	1.00	\$82.30
27	REAR BUMPER RH SIDE RETAINER / <i>x acc</i>	1.00	\$159.90
28	REAR BUMPER LH SIDE RETAINER / <i>acc</i>	1.00	\$159.90
29	REAR END PANEL / <i>acc</i>	1.00	\$735.70
30	REAR END PANEL TOP TRIM / <i>acc</i>	1.00	\$233.10

# Vin's

**Vin's Motor Pte Ltd**  
 160 Sin Ming Drive  
 #03-03 Sin Ming Autocity  
 Singapore 575722  
 Tel : 6453 2121 Fax : 6459 9795  
 GST Registration No. 199906067G

31	REAR SPARE TYRE PANEL <i>x 1/2 price</i>	1.00	\$781.70
32	REAR SPARE TYRE PANEL TOP COVER <i>- BT</i>	1.00	\$1,105.50
33	REAR SPARE TYRE PANEL INSULATOR <i>- TW</i>	1.00	\$455.20
34	REAR TOOL BOX <i>?</i>	1.00	\$491.60
35	REAR RH FENDER INNER TRIMBOARD <i>= 500</i>	1.00	\$741.80
36	REAR LH FENDER INNER TRIMBOARD	1.00	\$741.80
37	REAR FENDER INNER TRIMBOARD CLIPS @ \$3.50 <i>/ MLC</i>	20.00	\$70.00

\$16,167.78

Discount: -25%

(\$4,041.95)

\$12,125.83

38	REAR TAILGATE REVERSE CAMERA <i>- 4PM</i>	1.00	\$380.00
39	REAR BUMPER PARKING SENSOR <i>- 4PM</i>	1.00	\$280.00
40	REAR WINDSCREEN GLASS GUM <i>- MLC</i>	1.00	\$60.00
41	REAR NO. PLATE <i>- MLC</i>	1.00	\$40.00
42	TO REMOVE AND REFIX REAR WINDSCREEN	1.00	\$150.00 <i>120</i>
43	TO REMOVE AND REFIX REAR UNDERCARRIAGE	1.00	\$280.00 <i>XAVN</i>
44	TO REPAIR DAMAGES	1.00	\$1,600.00 <i>1200</i>
45	TO SPRAY PAINTING	1.00	\$1,300.00 <i>1200</i>

Subtotal w/o GST:

\$16,215.83

*10 Days.  
 P/P  
 before paint photos.  
 Gino Riop  
 28/10/21*

**LMK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplemental claims must be surveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
**Signature:**  
**Date:**

Issued by Raymond Teo

This is a computer-generated document. No signature is required.