

ASS. REC. BY:

REF:

A/G/21011805/Kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 6640 E Yr Regn: 01, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle c.c. 1496

Colour

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

128690

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK8 1200137

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Arivo

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

18/1/21

D.O.I.

5/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

KBS MOTORSPORTS PTE LTD



YOUR REF.: SMF8666R
OUR REF.: SLV6640E

TO: AIG
CC: MOTOR CLAIMS DEPARTMENT

FAX:

*Not Notified
11 Day &
Running After Paint
3 days*

DATE: 17 March 2022
FROM: Alvin Koh
FAX: 64525333
CONTACT: 81387188
MAKE & MODEL: HONDA SHUTTLE 1.5G CVT
CHASSIS NO.: GK81200137
ENGINE NO.: L15B5460170
YEAR MADE: 2017
ACCIDENT DATE: 18 January 2021

ESTIMATE FOR VEHICLE NO.: SLV6640E

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR WINDSCREEN MOULDING		1	\$ 184.70 ✓
2	REAR WINDSCREEN		1	\$ 1,082.60 +
3	TAILGATE		1	\$ 1,351.20 ✓
4	TAILGATE LOCK		1	\$ 498.60 X
5	TAILGATE STRIKER		1	\$ 118.90 X
6	TAILGATE CHROME TRIM		1	\$ 566.30 X
7	TAILGATE WEATHER SEAL		1	\$ 187.50 X
8	TAILGATE EMBLEM SHUTTLE		1	\$ 110.90 ✓
9	TAILGATE EMBLEM HYBRID		1	\$ 105.60 X
10	TAILGATE EMBLEM HONDA		1	\$ 102.80 ✓
11	TAILGATE INNER TRIM BOARD		1	\$ 787.20 X
12	TAILGATE LAMP LH		1	\$ 846.80 X
13	TAILGATE LAMP RH		1	\$ 846.80 X
14	BRAKE LAMP LH		1	\$ 995.10 X
15	BRAKE LAMP RH		1	\$ 995.10 X
16	REAR BUMPER		1	\$ 1,089.90 X
17	REAR BUMPER RETAINER LH		1	\$ 102.50 X
18	REAR BUMPER RETAINER RH		1	\$ 102.50 X
19	REAR BUMPER SIDE GRILLE LH		1	\$ 146.90 X
20	REAR BUMPER SIDE GRILLE RH		1	\$ 146.90 X
21	REAR BUMPER REFLECTOR LH		1	\$ 97.30 X
22	REAR BUMPER REFLECTOR RH		1	\$ 97.30 X
23	END PANEL TOP GARNISH		1	\$ 198.40 X
24	END PANEL		1	\$ 984.10 X

TOTAL: \$ 11,745.90
LESS 20% \$ (2,349.18)
PARTS TOTAL: \$ 9,396.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

KBS MOTORSPORTS PTE LTD
160 SIN MING DRIVE, #06-03
SIN MING AUTOCITY
6451 5333 / 6452 5333
COMPANY REG. NO.: 200504627K

Accident

SPECIAL NETT

BODY SEALANT	1	\$	nn	80.00	X
REAR NUMBER PLATE + HOLDER	1	\$	sn	60.00	X
REAR BUMPER CLIPS	10	\$	nn	100.00	X
REAR BUMPER REVERSE SENSOR	2	\$	sn	500.00	1

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$	2000	1,200.00	
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILIATE REPAIR	\$	nn	50.00	X
TO REMOVE & INSTALL REAR BOOT LID COMPONENT TO FACILIATE REPAIR	\$	600	80.00	
TO REMOVE & REPLACE REAR WINDSCREEN	\$		120.00	✓
TO REMOVE & REPLACE BUMPER SENSORS	\$	nn	120.00	X
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	150	250.00	X
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	150	50.00	
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	440	1,000.00	
TOTAL:	\$		13,006.72	
7% GST:	\$		910.47	
GRAND TOTAL:	\$		13,917.19	