



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21011092/Uqf3n2 Date: 09/11/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBS 9791S	Veh. Inspected	SJQ 3807L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2103221/RUC	Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG	Assign Date	29/10/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM RSZ (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	RN61083252	Colour	BLUE
Odometer	209001 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	WEST LAKE	7 mm
L/H Front Tyre	215/45 R17	WEST LAKE	7 mm
R/H Rear Tyre	215/45 R17	BRIDGESTONE	7 mm
L/H Rear Tyre	215/45 R17	BRIDGESTONE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/10/2021	Inspection Date	01/11/2021
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	