

ASS. REC. BY:

REF:

15/4 TM 12101194/Tinf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: **SHA 5955L**

at Workshop m/s _____

of _____

Insured: **SLM 3664D**Policy No. **MM000074**Claims No. **M2105005**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **2** days Res.: Yes or NoLum Sum: **20** % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: **Ms Luke** Vehicle: IN / OUTVeh No: **SHA 5955L**Yr Regn: **2017, Aug**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Prius**

c.c

1798Colour **Blue**

A/C: Insured / Std / NI / NA

Sp. Reading **567189**

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **STD KB3 F4 903563187**Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: **NI / S/Rim / STD A/Rim or**Tyre Size: **F: 195/65R15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **Worthake**

Front

Rear

R/Bal. **6** mmR/Bal. **6** mmL/Bal. **6** mmL/Bal. **6** mm

D.O.A. _____

D.O.I. **9/11/21**Survey held at **Comfort Legon**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirmed L/S \$1250, 2 repair days

(RED \$701.67; 36%)

Date/Time, File Pass to?

☐ : Prell. Report1) **25/11 TYPIST**☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: **TP**Lump Sum / L.S. (\$ **\$1250**)Days Of Repair: **2**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Wheelend (\$ _____)

S + RS. \$ _____

Photos

Others

TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

MVA: YY

LKK

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/10/2021
Vehicle Reg. No.:	SHA5955L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Vehicle Reg. Date:	10/08/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZRS060925	Chassis No:	JTDKB3FU903563187
Odometer:	567189 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,180.67
Miscellaneous Items	11.00
Labour	760.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,951.67
+ GST 7.00% (S\$)	136.62
Nett Amount (S\$)	2,088.29

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 29 Oct 2021)**Parts:** 144 TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA5955L/29/10/2021 15:15**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	de ✓ *499.90 FL
2	1		*REAR BUMPER CLIPS	25.00	0.00	nei ✓ *22.00 FL
3	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	↑ *318.80 FL xnn
4	1		*REAR BUMPER LOWER COVER	25.00	0.00	? *552.60 FL de ✓
5	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	rw ✓ *135.70 F
						1074.50
				Sub Total (\$)		1,529.00
				- List Item Discount on L Items (\$)	sn	805.87
						135.70
				Total Parts (\$)		1,180.67

F=Franchise part, L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA5955L/29/10/2021 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$)			11.00
			11

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 400.00
2	SPRAY PAINTING CHARGE	New	250 300.00
3	REMOVE/ REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (\$)			630 760.00

ComfortDelGro Engineering Pte Ltd/SHA5955L/29/10/2021 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

805.87
135.70
11
630
1582.57
1/s\$1250
2 days #

Tanpin 97495747
Wp 1/11/21 C 230pm
2 days
c/s Rony after repair
for the 1/11/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is of a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: