



Not Notion
Merry B4pam
Today
11 Sep 84900h



Lim Xuan Qing Victor
23 Jalan Raja Udang #28-09
Singapore 329216

File No : SH/2021/085/10/006/TP
Date : 06-March-2014

Estimated cost of repair for vehicle no : EK666L Toyota Alphard
Accident involving vehicle no: EK666L & GR1228B on 29.10.2021

Description	Quantity	Cost Price
LH rear door <i>BT ✓ 1872-60</i>	1	2856.80 ✓
LH rear door window regulator <i>?</i>	1	<i>DIT</i> 275.90 ✓
LH rear door lower moulding <i>?</i>	1	<i>my cm</i> 752.40 ✓
LH rear fender <i>BT ✓</i>	1	1521.60 ✓
LH rear fender wheel cowling <i>?</i>	1	<i>cm</i> 271.40 ✓
LH rear fender wheel cowling clips (1 Set) <i>?</i>	1	48.00 ✓
LH rear fender front lower garnish <i>in x</i>	1	288.60 x
LH rear fender window glass moulding <i>new 123.00</i>	1	895.70 ✓
Rear bumper <i>DIT/Bu ✓</i>	1	780.50 ✓
Rear bumper clips (1 set) <i>new ✓</i>	1	35.00 ✓
LH Rear bumper retainer <i>DIT ✓</i>	1	103.40 ✓

LH rear fender window glass sealant	1	S. nett	\$	<i>new</i> 60.00 <i>405ml</i>
LH rear fender window glass inner rubber seal	1	S. nett	\$	<i>new</i> 27.00 ✓

To remove and reinstall LH rear fender window glass and conduct water leak test \$ 100.00 *800*

To remove and install centre seats, rear seats, LH rear fender inner trim, floor carpet to facilitate repairs on LH rear fender \$ 120.00 *1000*

To remove damaged parts, to jack out LH rear fender inner panel, LH front door pillar, LH running board panel, and cut out damaged panels, to reweld, reshape and repair LH rear fender and inner panel, LH centre door pillar, to remove and refit door trim, lock, window, to replace damaged parts and adjust body panel alignment \$ 850.00 *7500*

To spray paint affected LH rear and inner damaged portion inclusive of preparatory works and material (Pearl paint) \$ 950.00 *8000*

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality \$ 25.00 *200*

T/Party: AIG Asia Pacific Insurance Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1
Accepted by Repairer