

Our Job Ref No : 305491476

Date : 14/10/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6548 8158

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SH 6054M

20/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2 The repair job shall bill to: CHINA YQ3146H

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$3,000.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : CHIANG

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : THEVAN

Name : THEVAN

Date : 11/11/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Vehicle No.: SH6054M
 Make : TOYOTA - 20.09.2017
 Model : PRIUS
 DOA : 20/10/2021

Date : 21.10.21
 Insurance: CHINA
 MVA : CHIANG /
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70
1	REAR TRUNK			\$1,126.60
1	REAR TRUNK COVER TRIM			\$254.40
1	REAR TRUNK LID LOGO (PRIUS)			\$52.90
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$60.80
1	TRUNK LID GLASS W/MOULDING UPPER			\$1,778.30
1	TRUNK LID GLASS W/MOULDING LOWER			\$1,569.70
1	REAR BUMPER			\$458.60
1	REAR BUMPER UNDER COVER			\$552.60
10	REAR BUMPER CLIP		\$2.20	\$22.00
2	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40
2	REAR BUMPER UNDER SIDE COVER /RH		\$232.00	\$232.00
1	REAR BUMPER UNDER COVER CENTRE			\$252.00
1	TAIL LAMP UPPER RH			\$557.90
1	TAIL LAMP LOWER RH			\$548.40
1	REAR SMART KEY ANTENNA			\$312.00
1	REAR BUMPER TOWING COVER			\$82.70
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$318.80
SUB TOTAL				\$9,369.20
LESS 25%				\$2,342.30
DISCOUNTED TOTAL				\$7,026.90
1	REAR TRUNK LID APPS STICKER			\$40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00
1	REAR NUMBER PLATE W/HOLDER			\$50.00
1	REAR BUMPER REVERSE SENSOR			\$135.70
				\$285.70
Labour Charge				
Panel Beating				\$950.00
Spray Painting Charge				\$800.00
Wiring Charge				\$60.00
Tuff Kote				\$90.00
Remove/Refix Reverse Sensor				\$60.00
TOTAL LABOUR				\$1,960.00
ESTIMATE TOTAL				\$9,272.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

thuan@lkhauto.com

82235769

21/10/21 1600

1/5 after repair photo

3 days swp