

ASS. REC. BY:

REF:

TH / 210111031/ke

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 59814

Yr Regn:

10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pina

c.c

1798

Colour

M.P. White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

94522

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB 3FU 803 09 2150

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Perilun

195/65R15

R:

Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

3

mm

L/Bal.

9

mm

L/Bal.

3

mm

D.O.A.

27/10/21

D.O.I.

29/10/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Got BT

1/11 @ 1822-43 Cahr

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5961H**

*Not Notchmark*  
*Recovery B4paint*  
*& 1822-43*

**AAD2110-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**29 OCT 2021****SHC5961H**

JTDKB3FU803092150

TOYOTA

PRIUS GEN 4

27/10/2021

*Ti*

09/10/2020

**PART****LIST**

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

\$	<i>Per</i>	485.60	<i>✓</i>
\$	<i>Per</i>	332.70	<i>✓</i>
\$	<i>Per</i>	22.00	<i>X</i>
\$	<i>Not 161</i>	374.50	<i>✓</i>
\$	<i>Per</i>	132.60	<i>X</i>
\$	<i>Per</i>	132.60	<i>X</i>
\$	<i>Per</i>	39.00	<i>X</i>
\$	<i>Per</i>	339.60	<i>X</i>
<i>N/C</i> \$	<i>(Cms)</i>	261.00	<i>X</i>
\$	<i>Per</i>	54.60	<i>✓</i>
\$	<i>Per</i>	54.60	<i>✓</i>
\$	<i>Per</i>	47.90	<i>✓</i>
\$	<i>Per</i>	913.60	<i>X</i>
\$	<i>Per</i>	126.70	<i>X</i>
\$	<i>Per</i>	651.00	<i>X</i>

**TOTAL \$ 3,968.00****25% \$ 992.00****\$ 2,976.00****Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR

\$	<i>Per</i>	700.00	<i>X</i>
\$	<i>Per</i>	95.00	<i>5050</i>
\$	<i>Per</i>	150.00	<i>X</i>
\$	<i>Per</i>	200.00	<i>X</i>
\$	<i>Per</i>	130.00	<i>X</i>
\$	<i>Per</i>	80.00	<i>3050</i>
\$	<i>Per</i>	80.00	<i>3050</i>
\$	<i>NIP</i>	180.00	<i>X</i>

*1822-43*  
*810*  
*1013-43*

**Trans-cab Auto Services Pte Ltd****AAD2110-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5961H**

1SET REAR BUMPER RETAINER CLIP	\$	nn	85.00	X
1 END PANEL TRIM CLIP	\$	nn	65.00	X
1SET BUMPER CLIP FRT	\$	nn	95.00	X
1 REAR NUMBER PLATE WITH MOULDING	\$	nn	200.00	X
<b>TOTAL</b>	<b>\$</b>		<b>2,060.00</b>	

<b>TOTAL PARTS</b>	<b>\$</b>		<b>5,036.00</b>	
--------------------	-----------	--	-----------------	--

**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	300.00	X
--	----	----	--------	---

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
---	----	----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	2001
---	----	--	----------	------

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	380.00	X
--	----	----	--------	---

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	nn	180.00	X
---	----	----	--------	---

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn	480.00	X
---	----	----	--------	---

To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn	480.00	X
---	----	----	--------	---

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	nn	380.00	X
--	----	----	--------	---

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
---	----	----	--------	---



**Trans-cab Auto Services Pte Ltd****AAD2110-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5961H**

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 250.00	X
Towing Fees	\$	<i>nn</i> 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	<i>4400</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>500</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>100</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 220.00	X
To replace, refix and top up coolant for radiator	\$	<i>4</i> 170.00	X
To lift-up / out engine with gear box and refit.	\$	<i>4</i> 440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	<i>4</i> 380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>4</i> 380.00	X
<b>TOTAL</b>	<b>\$</b>	<b>10,290.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>15,326.00</b>	

**(PART-BY-PART) Repair Days****25 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: