

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

29-Oct-21

## ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8811 T

1 pc	Tailgate	\$	2,480.40	XR
1 pc	Emblem "Hyundai"	\$	28.00	/nec
1 pc	Emblem "Hybrid"	\$	24.30	/nec
1 pc	Emblem "Ioniq"	\$	31.30	/nec
2 pcs	Rear n/s & o/s tail lamps	\$	725.20	X SUC
1 pc	Rear bumper	\$	459.40	/cut
1 pc	Rear bumper reinforcement	\$	294.80	? DT
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket	\$	20.00	? X SUC
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00	? X SUC
2 pcs	Rear bumper n/s & o/s stay	\$	276.20	X SUC / cut
2 pcs	Rear bumper n/s & o/s side bracket	\$	66.20	X SUC
1 pc	Rear bumper lower moulding centre	\$	216.50	/scr
1 pc	Rear bumper lower cover	\$	47.50	/DES
1 pc	Rear bumper cap hook	\$	9.10	/cut
2 pcs	Rear bumper n/s & o/s reflector	\$	63.80	X SUC

\$ 4,757.70  
\$ 951.54  
\$ 3,806.16

### S/N

1 set	Rear bumper clips
1 set	Reverse sensor
1 pc	Rear number plate with casing
1 set	Tailgate stickers

LKK Auto Consultants hence notified the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 48.00 /nec  
\$ 280.00 /cut  
\$ 50.00 /cra  
\$ 100.00 /nec  
\$ 50.00 X SUC  
\$ 50.00 20  
\$ 120.00 XNN  
\$ 120.00 30  
\$ 180.00 40  
\$ 850.00 360x 70  
\$ 800.00 360x  
\$ 120.00 20  
\$ 6,574.16

Sundry  
To check wiring  
To dismantle/refit rear tailgate window glass onto new tailgate  
To dismantle / replace reverse sensor to new bumper and reset to the same  
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.  
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc  
To putty and spray painting on rear bumper, end panel, rear bumper lower cover (Black), tailgate  
To apply rustproofing on the repaired and replaced panels.

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Theran@khanato.com  
82235769

29/10/21 1700

p/p hfr paint photo

3clays wp

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

2-Nov-21

## SUPPLEMENTARY ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8811 T

1 pc	Lamp assy (rear fog)	\$	201.50	✓ BR
1 pc	Rear bumper lip		\$47.50	✓ cut
		Less 20%	\$	49.80
				\$199.20

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

$$P = \$1636.10 - 20\% = \$1308.88$$

$$S/H = \$478.00$$

$$L = \$1370.00$$

---

$$\$3156.88$$

Repair days : 04.