

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011107/UVY3N2**Date:** 07/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00008552100
Claimant Vehicle No :	SJV4280Y	Insured Vehicle No :	SFF8287J
Date of Loss:	27/10/2021	Nature of Claim:	TP
		Claim No:	SNM21D206202/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV4280Y	Engine No:	HR15292890B
Make & Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Chassis No:	JN1BAAG11Z0110700
Reg. Date:	26/01/2010 (Man. Year: 2009)	Odometer:	147117 km
Colour:	Silver		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,922.93	1,711.36	2,211.57	56.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,360.00	570.00	29.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,852.93	3,071.36	2,781.57	47.52
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	5,852.93	2,450.00	3,402.93	58.14
+ GST 7.00/7.00% (S\$)	409.71	171.50	238.21	58.14
Nett Amount (S\$)	6,262.64	2,621.50	3,641.14	58.14

INSPECTION

Date of Assignment:	18/11/2021	
Date Inspected:	13/12/2021	Inspected At: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2022)

Parts: 143 NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJV4280Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR HANDLE-LH	Serviceable	173.30 FN	*- FN
2	1		*FRONT DOOR CHROME PROTECTOR-LH	Not fitted	38.50 FN	*- FN
3	1		*FRONT DOOR OUTER MOULDING-LH	Scratched	157.80 FN	*157.80 FN
4	1		*FRONT DOOR STICKER-LH	Not Necessary	26.30 FN	*- FN
5	1		*FRONT DOOR RUBBER-LH	Not Necessary	123.10 FN	*- FN
6	1		*REAR DOOR-LH	Dented/Bent	1,178.50 FN	*1,178.50 FN
7	1		*REAR DOOR HANDLE -LH	Serviceable	88.30 FN	*- FN
8	1		*REAR DOOR CHROME PROTECTOR-LH	Not fitted	38.50 FN	*- FN
9	1		*REAR DOOR OUTER MOULDING-LH	Scratched	157.80 FN	*157.80 FN
10	1		*REAR DOOR STICKER-LH	Necessary	26.30 FN	*26.30 FN
11	1		*REAR DOOR RUBBER-LH	Not Necessary	123.10 FN	*- FN
12	1		*SIDE MIRROR ASSY-LH	Serviceable	502.50 FN	*- FN
13	1		*SIDE MIRROR COVER-LH	Serviceable	165.20 FN	*- FN
14	1		*FRONT DOOR-LH	Repair	1,178.50 FN	*- FN
15	1		*SIDE SKIRT OUTER GARNISH-LH	Grazed	343.00 FS	*343.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	4,320.70	1,863.40
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	397.77	152.04
Total Parts (\$\$)	3,922.93	1,711.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS	New	-	-
2	TO KNOCK OUT DENTS ON CENTER PILLAR,REMOVE,REPLACE ACCIDENT PARTS	New	550.00	450.00
3	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,050.00	800.00
4	TO TRANSFER DOOR AND DOOR FITTINGS	New	160.00	60.00
5	TO CHECK WIRING	New	50.00	20.00
6	TO TUFF-KOTE	New	120.00	30.00
Gross Labour Cost (\$)			1,930.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >