



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC21009694/Ntf3e2-1	
			Date: 10/12/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YM 8741C	Veh. Inspected	SJY 5154G	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/024957	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	01/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALPHARD	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	AGH300263866	Colour	BLACK	
Odometer	13600 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40 R19	CST	6 mm	
L/H Front Tyre	255/40 R19	CST	6 mm	
R/H Rear Tyre	255/40 R19	CST	6 mm	
L/H Rear Tyre	255/40 R19	CST	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/09/2021	Inspection Date	16/09/2021	
Survey held at	EVERDAWN AUTO SERVICE 8 KAKI BUKIT AVE 4 #01-02 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	