

TRANS EUROKARS PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042 ESTIMATE COST OF REPAIRS

(5) EUROKARS SERVICES

CHINA TAIPING INSURANCE P/L NAME :									WIP:		10885
ANSC	N ROAD		ADDRESS :						EXCESS:		
# 16-00	SPRINGLEAF TO	WER							DATE:	2	7-Oct-21
SINGAF	PORE 079909										
ATTN.	: :	MOTOR CLAIMS	TEL:								
FAX :											
VEH NO	0:	SCM448M	DATE IN :					CONTACT PERSON :	RONALD		
CHASS	IS NO :	MM6DL2SAAGW186202	MILEAGE :					TYPE OF CLAIM :	THIRD PARTY (LAIN	Л
MODE		MAZDA 2	DATE REG.	:	2	8-Apr-1	6	POLICY NO. :			
						OF WOR					
				Pa	arts De	scriptio	<u>n</u>				
NO		DESCRIPTION			QTY	1st	Supp	PARTS NO	REVISED		PRICES
1	REAR BUMPER				1			MDB7A-50-221BBB	le	\$	954.50
2	STAY,REAR BUMPER				2			MDB7A-50-271	2 nn	\$	26.00
_	RETAINER LH REAR				1			MDB7A-50-2J1	× n^	\$	22.80
	BRACKET LOWER REAR BUMPER				1			MDB7H-50-251	Xnn	\$	24.40
	CLIP CLIP				1			MGJ21-50-049	NOI-	\$	3.40
	FASTENER				7			MB45A-56-146A	ali-	\$	21.00
	REFLECTOR LH		_		1			MD350-51-5L0E	Xn	\$	53.00
-	SPLASH SHIELD LH REAR				1			MDB7A-50-350	XNN	\$	55.60
	STONE GUARD LH			+	1			MDB1L-50-4R2	X nn	\$	14.70
_	TAIL LAMP LH				1			MDB7A-51-160B	Xnn	\$	395.30
_	GASKET TAIL LAMP RH				1			MDB7A-51-153	w	\$	33.50
	GASKET TAIL LAMP LH				1			MDB7A-51-163	Ne /	\$	33.50
· ·	REAR END PANEL				1			MDBYA-70-75Z	% 1 ×	\$	656.00
	PLATE CORNER LH REAR				1			MDBYA-71-490		_	41.30
15	PANEL REAR FENDER LOWER LH				1			MDBYB-71-40XA	XYAN	\$	287.70
16	CHAMBER,EXTRACTOR				1			MD350-51-920A	(X)	\$	74.90
	23							TOTAL PARTS		\$	2,697.60
								TOTAL PARTS COST		\$	2,697.60
				SLIE	DDIF	MENT	\RV				-
NO DESCRIPTION				SUPPLEMENTARY QTY 1st Sup			Supp	PARTS NO REVISE		PRICES	
1	DESCRIPTION			+	٠.١	136	344	1700	KEVISED	-	. 111013
2				+							
3						•					
								TOTAL PARTS		\$	-
								TOTAL PARTS COST		\$	-
								1.2		1	

ESTIMATE Page 1 of 3

_			<u>Labour Description</u>		REVISE	<u> </u>	PR	ICES	
								-	
1		TO REPLACE REAR BUMPER, REAR EN AREAS AFFECTED BY THE ACCIDENTS		FENDER LOWER AND REPAIR	660	> \$	2,	,640.00	
2		TO RESPRAY REAR BUMPER,REAR EN AFFECTED BY THE ACCIDENTS.	D PANEL,PANEL REAR FEN	DER LOWER AND AREAS	630	> √\$	2	,520.00	
3 1	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALAN	IT ON THE CUTTING	NΩ	X NETT	\$	í	360.00	
4 N	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.			(80	\$	<u>;</u>	660.00	
5 1	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR	PROPER FUNCTIONING.		120	> \	>	250.00	
6 N	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCID	DENT REPAIR WORKS.		(80	· 🗸 🔅	>	300.0	
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESEF	RVATION.(INCLUDING NEW	PARTS AND CAOUTCHOUC)	M ×		5	250.0	
8 1	MZ-BR-SUNDRI	SUNDRIES.			20.	✓ 5	\$	50.0	
	REMARKS:			TOTAL LABOUR	\$	- 5	\$ 7	7,030.0	
7	THIS IS ONLY AN	ESTIMATE FROM VISUAL INSPECTION A	AND	TOTAL PARTS	\$	- !	\$ 2	2,697.6	
		BE MORE DAMAGES FOUND DURING TI		TOTAL	\$	- !	\$ 9	9,727.6	
		OU WILL BE INFORMED BEFORE THE R		LESS EXCESS	\$	- 5	\$	-	
		OUT.TAKE NOTE THAT SHOULD YOU DE TH THE REPAIRS, A QUOTATION FEE O		TOTAL AFTER EXCESS	\$	- 5	\$ 9	9,727.6	
		O ACCORDINGLY FOR MAN-HOURS INVO	GST 7%	\$	- !	\$	680.9		
5	SOURCING FOR	PARTS PRICE AS WELL AS LABOUR CHAP	RGES.	GRAND TOTAL	\$	- !	\$ 10	0,408.5	
		SUPPLEMENTARY LAE	BOUR DESCRIPTION		,				
					REVISE	D	PI	RICES	
1		#N/A							
2		#N/A							
	REMARKS:			TOTAL LABOUR	\$	-	\$	-	
	THIS IS ONLY AN	I ESTIMATE FROM VISUAL INSPECTION	AND	TOTAL PARTS	\$	-	\$	-	
SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCE OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS AF BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400				TOTAL	\$	- 1	\$	-	
				LESS EXCESS	\$	-	\$	_	
				TOTAL AFTER EXCESS	\$	-			
		D ACCORDINGLY FOR MAN-HOURS INV		GST 7%	\$	-	\$	-	
		PARTS PRICE AS WELL AS LABOUR CHA		GRAND TOTAl sultants hence	e Sotify	-	\$	-	
ĺ	ply lo	97495749/6256 9/11/21 (1015 ourney before paint days 2 16hanto.am	TRA	TRA NS FUROKARS PT Entry painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					