



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623		Ref: CS/SMO21011121/Aqf3e2	Date: 09/12/2021
		Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGZ 9973M	Veh. Inspected	SGX 7586X
Policy No.	D21MTPV01014869	Coverage (\$)	0.00
Claim No.	CMTD2103232/MYE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	01/11/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMRN68407S200536	Colour	WHITE
Odometer	177779 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R17	TOURADOR	6 mm
L/H Front Tyre	225/45 R17	TOURADOR	6 mm
R/H Rear Tyre	225/45 R17	TOURADOR	6 mm
L/H Rear Tyre	225/45 R17	TOURADOR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/10/2021	Inspection Date	01/11/2021
Survey held at	F-1 AUTOCLINIC PTE LTD 25 KAKI BUKIT ROAD 4 #05-26 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	