

F-1 AUTOCLINIC PTE LTD

25 KAKI BUKIT ROAD4 # 05-26 SYNERGY @KB Singapore 417800

01st NOV 2021

25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

TP Sampo
Xiao Chan

Accident date: 28th OCT 2021

Estimated repair cost for vehicle no: SGX7586X HONDA STREAM 1.8X A '07 (COE TIL SEP 2022)

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear Boot Lid <i>Distorted</i>		\$1,171.30 <i>903.</i>
2	2	Rear Boot Lid shock absorber <i>new</i>	\$168.70	\$337.40 <i>+</i>
3	1	Rear boot lid stream logo <i>new</i>		\$35.80 <i>+</i>
4	8	Rear boot lid center moulding clips <i>new</i>	\$5.50	\$44.00 <i>+</i>
5	1	Rear boot lid center moulding		\$215.00 <i>+</i>
6	1	Rear boot lid emble logo <i>new</i>		\$55.00 <i>+</i>
7	1	Rear Boot Lid windscreen seal <i>new</i>		\$92.10 <i>+</i>
8	1	Rear Boot Lid Number Plate <i>Best.</i>		\$50.00 <i>+</i>
9	1	Rear Boot Lid Inner Lock <i>Jammed</i>		\$285.00 <i>+</i>
10	1	Rear boot lid inner rubber <i>lit</i>		\$215.00 <i>+</i>
11	1	Rear Boot Lid Inner Trim board <i>new</i>		\$412.00 <i>+</i>
12	2	Rear tail lamp <i>Lit cracked.</i>	\$485.00	\$970.00 <i>-385</i>
13	4	Rear tail lamp clips <i>new</i>	\$5.50	\$22.00 <i>10.</i>
14	2	Rear tail panel <i>new</i>	\$306.70	\$613.40 <i>+</i>
15	1	Rear tail lamp lower panel <i>new</i>		\$245.10 <i>+</i>
16	1	Rear Bumper <i>Distorted</i>		\$1,377.00 <i>683.</i>
17	2	Rear Bumper Side Bracket <i>new</i>	\$85.00	\$170.00 <i>70</i>
18	8	Rear bumper clips <i>new</i>	\$6.50	\$52.00 <i>30</i>
19	1	Rear Bumper reverse sensor <i>Damaged.</i>		\$350.00 <i>200(S.N.)</i>
20	1	Rear End Panel outer <i>Dented</i>		\$425.00 <i>+</i>
21	1	Rear End Panel inner <i>Dented</i>		\$251.00 <i>+</i>
22	1	Rear End Panel Top Garnish <i>Dented</i>		\$215.00 <i>+</i>
23	2	Rear floor panel top cover	\$160.00	\$320.00 <i>+</i>
24	1	Rear floor panel inner trim board		\$327.60 <i>+</i>
25	1	Rear floor panel sealant		\$250.00 <i>+</i>
26	1	Rear spare tire bracket		\$243.10 <i>+</i>

Subtotal :- \$8,743.80

3649.90 S.N: 200
2919.92

labour charges

To remove & re-fix rear windscreen

\$120.00 ✓

Gum

\$50.00 ✓

To remove & re-fix cushion

~~\$120.00~~ 80

To remove & re-fix rear exhaust

\$0.00 x

To remove & re-fix reverse sensor

~~\$120.00~~ 50

To Check Wiring System

~~\$80.00~~ 30

Tuff Kote

2410.

~~\$120.00~~ 80

Towing charges

\$0.00 x.

Panel beating

~~\$1,200.00~~ 1000

Spray painting

~~\$1,200.00~~ 1000.

Subtotal :- \$3,010.00

Total:- \$11,753.80

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 552992.

4/s: 381c (Nett Value).

07 Days