

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

Vehicle Nos : **SLX 2993 C**

Model : Mercedes CLA180

Year : 2015

Chassis No : WDD1173422N134238

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 2,487.90	\$ 2,487.90
2	Bootlid logo	1	\$ 110.00	\$ 110.00
3	Bootlid weather strip	1	\$ 168.00	\$ 168.00
4	Bootlid inner lock assy	1	\$ 274.00	\$ 274.00
5	Rear bumper	1	\$ 1,786.00	\$ 1,350.00 1,786.00
6	Rear bumper lower	1	\$ 686.30	\$ 686.30
7	Rear bumper lower center garnish	1	\$ 275.30	\$ 156.68 275.30
8	Rear bumper reinforcement	1	\$ 698.00	\$ 698.00
9	Rear bumper centre beam garnish	1	\$ 213.90	\$ 162.00 213.90
10	Rear bumper bracket	3	\$ 145.00	\$ 435.00
11	Rear bumper side retainer	2	\$ 125.00 156.00	\$ 250.00 312.00
12	Rear bumper reverse sensor	2	\$ 250.00 265.00	\$ 500.00 1,590.00
13	Rear bumper heat shield	1	\$ 288.00	\$ 288.00
14	Rear bumper tow cap	1	\$ 125.00	\$ 125.00
15	Rear end panel outer	1	\$ 1,125.00	\$ 1,125.00
16	Rear end panel inner	1	\$ 995.00	\$ 995.00
17	Rear end panel top garnish	1	\$ 215.00	\$ 215.00
18	Taillamp	2	\$ 598.00 730.00	\$ 598.00 1,460.00
19	Taillamp outer garnish	2	\$ 180.00	\$ 360.00
20	Taillamp bracket	2	\$ 49.00	\$ 98.00
21	Rear exhaust pipe chrome tip	2	\$ 345.00	\$ 690.00
22	Rear exhaust pipe heat shield	1	\$ 181.60	\$ 181.60

Parts Sub Total : \$ 3114.68 14,574.00

10%

Discount : \$ 311.47 1,457.40

PARTS TOTAL : \$ 13,116.60

2803.21

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ -80.00
2	Bootlid sealant	1	\$ 100.00	\$ 100.00
3	Bootlid wrap sticker <i>provide invoice</i>	1	\$ 480.00	\$ * 480.00
4	Rear bumper clips	1	\$ 60.00	\$ 30.00 60.00
5	Rear bumper lower clips	1	\$ 60.00	\$ 60.00
6	Rear bumper reverse sensor seal <i>2</i>	<i>6</i>	\$ 58.00	\$ 116.00 348.00
7	Rear bumper wrap sticker <i>provide invoice</i>	1	\$ 580.00	\$ * 580.00
8	Rear end panel sealant	1	\$ 100.00	\$ 100.00
9	Rear end panel top garnish clips	1	\$ 60.00	\$ 60.00
10	Taillamp clips	2	\$ 60.00	\$ 120.00
11	Taillamp seal <i>1</i>	<i>2</i>	\$ 30.00 60.00	\$ 30.00 120.00
SPECIAL NETT TOTAL :				\$ 176.00 2,108.00

NNX
NNX
CUTV
NEC
NNX
NECV
CUTV
NNX
NNX
NSX
NECV

Nos.	LABOUR	S\$
1	R&R rear bumper reverse sensor	\$ 60.00 100.00
2	R&R rear exhaust pipe	\$ 150.00
3	Diagnostic reset fault code	\$ 300.00
4	Conduct water leak test	\$ 180.00
5	Check wiring	\$ 100.00
6	Upholsterty	\$ 300.00
7	Panel beating	\$ 400.00 1,400.00
8	Rust proofing	\$ 200.00
9	Spray painting	\$ 200.00 1,400.00
LABOUR TOTAL :		\$ 660.00 4,130.00

NNX
NNX
NNX
NNX
NNX
NNX
NNX
NNX

Survey 1/11/2021
Resurvey 2/11/2021
1615 hrs
Termin

* Provide invoice
to amend estimate

PARTS TOTAL : \$ 13,116.60
SPECIAL NETT TOTAL : \$ 2,108.00
LABOUR TOTAL : \$ 4,130.00
GRAND TOTAL : \$ 19,354.60

Lump sum repair
Repair days 5

Parts 2803.21
+ invoice 4234 SN 1176.00
Labour 660.00
4,639.21
@ 20 % 927.84
3711.37

LS 3,700/2

Termin
2/11/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:



INVOICE

Team Auto.

Invoice Date
15 Nov 2021

Invoice Number
INV-4234

Coatconut Pte Ltd
33 Ubi Ave 3
Vertex
#01-36
Singapore 408868

Description	Quantity	Unit Price	Amount SGD
Wrapping Full Rear Bumper Boot Lip	1.00	1,000.00	1,000.00
Mercedes CLA 180 AMG Line SLX 2993C			
Subtotal			1,000.00
TOTAL SGD			1,000.00

Due Date: 30 Nov 2021

Coatconut Pte Ltd UEN:201735742Z
OCBC Current Account 543184469001

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Received 18/11/2021
1058 hrs

TGwin Mue