

ASS. REQ. BY:

REF: MSG/21011129/KV f3Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: YP 6088C

Policy No. 1001361026

Claims No. 264819

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 819K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBC 6399XYr Regn: 04, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Dynac.c. 2982Colour Silver

AC: Insured / Std / NI / NA

Sp. Reading 349497

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT 35440K 202265Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: MT / S/Rim / STD A/Rim orTyre Size: F: 195R15X8R: 155R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 7 7 mmL/Bal. 6 mmL/Bal. 7 7 mmD.O.A. 30/10/21D.O.I. 2/11/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Mea c/s & 15m

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/11/21 LS \$7450 confirmed by email (Red 3967.79, 34%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 12Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

2) 23/11/21-typist

Report Format: Merimen

Lump Sum / L.B.I: (\$ 7450)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

Not Authorised

WS Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 30/10/2021

TP Veh Reg No: YP6088C

*1/1 Reg &
 Accruing After Repair*

Estimate No: ES2191048/YISHUN

Date: 01 Nov 2021

Policy No: DMCG21004787

Veh Reg No: GBC6399X

Make/Model: TOYOTA TOYOTA
 DYNA 150 MANUAL

Chassis No: JTFAT35Y40K202265

Engine No: 1KD2279496

Reg. Date: 22/04/2013

12 days

Estimate Repair Cost to Vehicle No :GBC6399X

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	398.57	1 PC	<i>Bt</i> 398.57	✓
2 FRONT GRILLE	516.60	1 PC	<i>pd/wap</i> 516.60	✓
3 FRONT GRILLE LOGO	70.35	1 PC	<i>mu</i> 70.35	✓
4 FRONT GRILLE INNER RUBBER	40.80	1 PC	<i>mu</i> 40.80	✓
5 RH HEADLAMP	795.00	1 PC	<i>CMA</i> 795.00	✓
6 FRONT PANEL	1,126.00	1 PC	<i>Bt</i> 1,126.00	✓
7 FRONT PANEL EMBLEM	70.90	1 PC	<i>mu</i> 70.90	✓
8 FRONT PANEL TOP CENTRE GARNISH	342.80	1 PC	<i>pd/wap</i> 342.80	✓
9 FRONT CHASSIS CROSS MEMBER	222.60	1 PC	222.60	?
10 RH TAILLAMP	210.70	1 PC	210.70	?
11 RH TAILLAMP PANEL	102.80	1 PC	<i>Bt</i> 102.80	✓
12 FRONT LH SIDE MIRROR STAY	369.70	1 PC	<i>Bt</i> 369.70	✓
13 FRONT LH SIDE MIRROR ROUND	183.00	1 PC	<i>mu</i> 183.00	✓
14 FRONT WINDSCREEN GLASS RUBBER	323.23	1 PC	<i>mu</i> 323.23	<i>50/1m</i>
			4,773.05	
		Less 25%	1,193.26	3,579.79
Special Net				
15 FRONT NUMBER PLATE	18.00	1 PC	<i>Bt</i> 18.00	✓
16 STICKER - 70KM/H	10.00	1 PC	<i>mu</i> 10.00	✓
17 REVERSE SENSOR	200.00	1 SET	<i>pd</i> 200.00	✓
18 FRONT RH DOOR COY STICKER	20.00	1 PC	<i>mu</i> 20.00	✓
19 RH TAILGATE ASSY	900.00	1 PC	<i>Bt</i> 900.00	✓
20 RH CANOPY BOX PILLAR	300.00	1 PC	<i>Bu</i> 300.00	✓
21 TAILGATE LOCK ASSY	480.00	1 PC	<i>Bt</i> 480.00	✓
22 RH TAILGATE LOWER HINGE	150.00	1 PC	<i>Bt</i> 150.00	✓
23 CANOPY REAR RH SIDE PANEL	400.00	1 PC	<i>Bu</i> 400.00	✓
			2,478.00	2,478.00
Labour				
24 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402
ATTN: Motor Claim Department

WS Ref: TP/MSIG
Claim Type: Third Party
Accident Date: 30/10/2021
TP Veh Reg No: YP6088C

Estimate No: ES2191048/YISHUN
Date: 01 Nov 2021
Policy No: DMCG21004787
Veh Reg No: GBC6399X
Make/Model: TOYOTA TOYOTA
DYNA 150 MANUAL
Chassis No: JTFAT35Y40K202265
Engine No: 1KD2279496
Reg. Date: 22/04/2013

Estimate Repair Cost to Vehicle No :GBC6399X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
25 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,TO CUT,WELD & RENEW FRT PANEL,FRT MAIN CHASSIS MEMBER & REALIGN THE SAME	900.00	1 LA	900.00	600
26 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
27 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
28 PUTTY & RESPRAY ON FRT PANEL,GRILLE,FRT RH DOOR,REAR RH PILLAR,BUMPER & ALL FRT AFFECTED AREAS	950.00	1 LA	950.00	850
29 REMOVE & REFIX RH TAILLAMP & PANEL,TO KNOCK & REPAIR REAR END FLOOR BOARD PANEL & REALIGN THE SAME INCLUDING REMOVE & REFIX REAR TRUCK	1,000.00	1 LA	1,000.00	
30 PUTTY & RESPRAY ON RH TAILGATE,PILLAR,REAR END PANEL & ALL REAR AFFECTED AREAS	600.00	1 LA	600.00	400
31 REMOVE & REFIX RH TAILGATE,RH SIDE GATE,TO CUT,WELD & RENEW REAR RH SIDE PANEL,REAR RH CORNAL PILLAR & REALIGN THE SAME INCLUDING SUPPLY ALL NECESSARY MATERIAL	1,500.00	1 LA	1,500.00	1500
			5,360.00	5,360.00

Total S\$ 11,417.79

Add GST @ 7% 799.25

Total Amount Payable S\$ 12,217.04

LKK Auto Consultants hence notify **Cheng Hoe Motor Pte Ltd**
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

AUTHORISED SIGNATURE

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 30/10/2021 18:23 (SGT)
Date of Accident 30/10/2021 12:50 (SGT)
Exact Location of Accident Singapore
Additional Location Information TUAS ROAD BEFORE ROUNDABOUT TOWARDS AYE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBC6399X
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner 123 HOME PLUMBING PTE.LTD
Company Reg No 2XXXXX908M
Email Address 123homeplumbing@gmail.com
Mobile Phone No (Phone) +65-82331138
Alternative Phone No +65-82331138

VEHICLE PARTICULARS

Manufacturer Toyota
Model DYNA 150 MANUAL
Variant
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Manual
CC 2982


INSURANCE COMPANY

Name of Insurance Company ERGO Insurance Pte. Ltd.
Type of Coverage ThirdParty
Fleet Policy No
Policy Number DMCG21004787
Cover Note Number 22/4/21-21/4/22

DRIVER

Name of Driver NG YEW KWANG
NRIC No SXXXX947B

Sketch Plan



A = GBC 6399X

B = YP 6088C

Lam Weng Soon

S9722951A

NP: 92353364

C = GBC 2887M

Tan King Xi

G 8053450M

NP: 82641699

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Doa: 30/10/21

Time: 1250pm.

I stop behind m/van (C) before the roundabout as there were oncoming vehicles in the roundabout. Out of sudden, I felt a great impact at back and my lorry move forward and hit onto the rear of van (C). I came down and noticed my vehicle is involved in a chain accident of total 3 vehicles.

Driver of m/lorry (B) which hit onto my rear apologized for the collision and we exchanged particulars.

NO injuries on anyone. I was alone. It was after rain and road was wet.



Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *Evelyn*
NRIC/FIN No.:

30/10/21

(YS)

() Claim Own Policy (☒) Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()