

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 30/10/2021

TP Veh Reg No: YP6088C

Estimate No: ES2191048/YISHUN

Date: 01 Nov 2021

Policy No: DMCG21004787

Veh Reg No: GBC6399X

Make/Model: TOYOTA TOYOTA
DYNA 150 MANUAL

Chassis No: JTFAT35Y40K202265

Engine No: 1KD2279496

Reg. Date: 22/04/2013

Not Authorised
11/Long 87650/1
Permy After Paint
12 days

Estimate Repair Cost to Vehicle No :GBC6399X

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 FRONT BUMPER	398.57	1 PC	B ₁ 398.57	✓
2 FRONT GRILLE	516.60	1 PC	516.60	✓
3 FRONT GRILLE LOGO	70.35	1 PC	70.35	✓
4 FRONT GRILLE INNER RUBBER	40.80	1 PC	40.80	✓
5 RH HEADLAMP	795.00	1 PC	795.00	✓
6 FRONT PANEL 1126	1,126.00	1 PC	B ₁ 1,126.00	✓
7 FRONT PANEL EMBLEM	70.90	1 PC	70.90	✓
8 FRONT PANEL TOP CENTRE GARNISH	342.80	1 PC	342.80	✓
9 FRONT CHASSIS CROSS MEMBER	222.60	1 PC	222.60	✓
10 RH TAILLAMP	210.70	1 PC	210.70	✓
11 RH TAILLAMP PANEL	102.80	1 PC	102.80	✓
12 FRONT LH SIDE MIRROR STAY 369.70	369.70	1 PC	369.70	✓
13 FRONT LH SIDE MIRROR ROUND	183.00	1 PC	183.00	✓
14 FRONT WINDSCREEN GLASS RUBBER	323.23	1 PC	323.23	50% ✓
			4,773.05	
		Less 25%	1,193.26	3,579.79
Special Net				
15 FRONT NUMBER PLATE	18.00	1 PC	18.00	✓
16 STICKER - 70KM/H	10.00	1 PC	10.00	✓
17 REVERSE SENSOR	200.00	1 SET	200.00	✓
18 FRONT RH DOOR COY STICKER	20.00	1 PC	20.00	✓
19 RH TAILGATE ASSY	900.00	1 PC	900.00	✓
20 RH CANOPY BOX PILLAR	300.00	1 PC	300.00	✓
21 TAILGATE LOCK ASSY	480.00	1 PC	480.00	✓
22 RH TAILGATE LOWER HINGE	150.00	1 PC	150.00	✓
23 CANOPY REAR RH SIDE PANEL	400.00	1 PC	400.00	✓
			2,478.00	2,478.00
Labour				
24 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG

Claim Type: Third Party

Accident Date: 30/10/2021

TP Veh Reg No: YP6088C

Estimate No: ES2191048/YISHUN

Date: 01 Nov 2021

Policy No: DMCG21004787

Veh Reg No: GBC6399X

Make/Model: TOYOTA TOYOTA
DYNA 150 MANUAL

Chassis No: JTFAT35Y40K202265

Engine No: 1KD2279496

Reg. Date: 22/04/2013

Estimate Repair Cost to Vehicle No :GBC6399X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
25 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,TO CUT,WELD & RENEW FRT PANEL,FRT MAIN CHASSIS MEMBER & REALIGN THE SAME	900.00	1 LA	900.00	600
26 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
27 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
28 PUTTY & RESPRAY ON FRT PANEL,GRILLE,FRT RH DOOR,REAR RH PILLAR,BUMPER & ALL FRT AFFECTED AREAS	950.00	1 LA	950.00	850
29 REMOVE & REFIX RH TAILLAMP & PANEL,TO KNOCK & REPAIR REAR END FLOOR BOARD PANEL & REALIGN THE SAME INCLUDING REMOVE & REFIX REAR TRUCK	1,000.00	1 LA	1,000.00	
30 PUTTY & RESPRAY ON RH TAILGATE,PILLAR,REAR END PANEL & ALL REAR AFFECTED AREAS	600.00	1 LA	600.00	400
31 REMOVE & REFIX RH TAILGATE,RH SIDE GATE,TO CUT,WELD & RENEW REAR RH SIDE PANEL,REAR RH CORNAL PILLAR & REALIGN THE SAME INCLUDING SUPPLY ALL NECESSARY MATERIAL	1,500.00	1 LA	1,500.00	1500
			5,360.00	5,360.00

Total S\$ 11,417.79

Add GST @ 7% 799.25

Total Amount Payable S\$ 12,217.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE