



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2202774
3 ANSON ROAD #16-00	INV Date	17/05/2022
SPRINGLEAF TOWER	Reference	CC6/CTI21011131/Rga3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SKZ 3354S
Insured Veh.	SMD 4153R
Claim No.	SNM21D206229
Policy No.	DMPCSNW00013552100
Accident Date	30/10/2021
Inspection Date	01/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC6/CTI21011131/Rga3q2

Date: 17/05/2022

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMD 4153R	Veh. Inspected	SKZ 3354S
Policy No.	DMPCSNW00013552100	Coverage (\$)	0.00
Claim No.	SNM21D206229	Excess (\$)	0.00
Assign From		Assign Date	01/11/2021

2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI 1.2 DIG-T CVT	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	SJNFEAJ11U1553578	Colour	BROWN
Odometer	59967 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
L/H Front Tyre	215/60 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	215/60 R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/10/2021	Inspection Date	01/11/2021
Survey held at	39 WOODLANDS INDUSTRIAL PARK E9 #05-04		
Repairer	AUTOMOTIVE REPAIR CENTRE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3354S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	820.00	820.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER	SCRATCHED	520.00	520.00
1	REAR REINFORCEMENT	BENT	700.00	700.00
1	REAR REINFORCEMENT BRACKET LH	BENT	150.00	150.00
1	REAR SPONGE	NOT NECESSARY	140.00	-
1	REAR RETAINER LH	NECESSARY	50.00	50.00
1	REAR FENDER ARC GARNISH LH	DEFORMED	500.00	500.00
1	REAR FENDER SHIELD LH	NOT NECESSARY	220.00	-
1	REAR TAIL LAMP LH	NOT NECESSARY	320.00	-
1	REAR REFLECTOR LH	SCRATCHED	80.00	80.00
1	END PANEL (ADDITIONAL)	BENT	580.00	580.00
	LESS 30% DISCOUNT		-	-1,035.00
			4,130.00	2,415.00
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
			200.00	200.00
<u>LABOUR</u>				
	SPRAY PAINTING REAR BUMPER ,TAILGATE ,REAR FENDER LH AND END PANEL INCLUDE BLENDING.		800.00	600.00
	REPAIR AND REPLACE AFFECTED ACCIDENT PARTS.		800.00	600.00
	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR .		100.00	40.00
	REMOVE AND REPLACE REAR EXHAUST PIPE AND SILENCER ,REALIGN.	NOT NECESSARY	200.00	-
	APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.		100.00	40.00
	CHECK AND RECTIFY ELECTRICAL WIRING.	NOT NECESSARY	30.00	-
			2,030.00	1,280.00
GRAND TOTAL			6,360.00	3,895.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00
---	--	--	-----------------

Report Ref No. CC6/CTI21011131/Rga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 3354S

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKZ 3354S

RE-INSPECTION

