



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2111-230
DATE : 1-Nov-2021
POLICY NO. : DAMT/00752586/01
VEHICLE REG. NO. : SKZ3354S
VEHICLE MAKE : NISSAN / QASHQAI 1.2 DIG-T CVT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>de</i>	1	\$ 820.00	\$ 820.00
2	Rear Bumper Clips <i>me</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Lower <i>scr</i>	1	\$ 520.00	\$ 520.00
5	Rear Reinforcement <i>bt</i>	1	\$ 700.00	\$ 700.00
6	Rear Reinforcement Bracket LH <i>bt</i>	1	\$ 150.00	\$ 150.00
7	Rear Sponge <i>x</i>	1	\$ 140.00	\$ 140.00
9	Rear Retainer LH <i>me</i>	1	\$ 50.00	\$ 50.00
10	Rear Fender Arc Garnish LH <i>de</i>	1	\$ 500.00	\$ 500.00
11	Rear Fender Shield LH <i>x</i>	1	\$ 220.00	\$ 220.00
13	Rear Tail Lamp LH <i>x</i>	1	\$ 320.00	\$ 320.00
14	Rear Reflector LH <i>scr</i>	1	\$ 80.00	\$ 80.00
Total Spare Parts				\$ 3,550.00
SPECIAL NETT				
15	Reverse Sensor <i>aw</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 200.00
LABOUR				
16	Spray Painting Rear Bumper, Tailgate, Rear Fender LH and End Panel include Blending	1	\$ 800.00	\$ 800.00
17	Repair and Replace Affected Accident Parts	1	\$ 800.00	\$ 800.00
18	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 100.00	\$ 100.00
19	Remove and Replace Rear Exhaust Pipe and Silencer, Re-align	1	\$ 200.00	\$ 200.00
20	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
21	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,030.00
Amount Before Excess				\$ 5,780.00
Add GST @ 7%				404.60
Total Amount Payable				\$ 6,184.60

2870
306
2009
X
X
X

200

600
400
600
40
1280
X
X

Estimate prepared by: Oscar Pong

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 2009
s/n - 200
L - 1280
Suppl - 406
3895
206
3116
4/5 - \$3,000

Rasul
Ap 90010068
5 days
L/S
01/11/21 @ 1510
Resurvey after repair