

YEW TEE AUTOMOBILE TECH PTE LTD

Branch: 39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)

Tel: 6256 2081(3Lines)

EMAIL: utauto2@singnet.com.sg

ROC: 200311009C GST: 200311009C

Website: www.ytauto.com.sg

Qty.	Description Of Parts		Pricing
1	FRONT SIDE MIRROR ASSY RH <i>SUN</i>	1218.60	\$ 1,218.60
1	FRONT SIDE MIRROR COVER RH <i>XAN</i>	52	\$ 146.20 <i>X</i>
1	FRONT SIDE MIRROR GLASS RH <i>XAN</i>	1157.67	\$ 438.60 <i>X</i>

List \$ 1,803.40
Less 5% \$ 90.17
Total \$ 1,713.23

LABOUR

To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools.

To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available.

\$ 200.00 *100*

\$ 250.00 *100*

LABOUR \$ 450.00

Sub Total. \$ 2,163.23
7% GST \$ 151.43
Grand Total \$ 2,314.66

1157.67

200.00

1357.67

209

1086.13

4S - \$1,050 / 2 days

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 900 100 68
2 days

4/5

02/11/21 @ 1450

Reg after repair