

A19

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

30/10/2021

Owner: NEO LAY HOON

ESTIMATE TO REPAIR NISSAN SERENA - SMR3276C

1pc	Rear tailgate	nett	\$	1,850.00
1pc	Rear tailgate windscreen moulding	nett	\$	195.00
1pc	Rear tailgate "Highway Star" emblem	nett	\$	55.00
1pc	Rear tailgate "E-Power" emblem	nett	\$	75.00
1pc	Rear tailgate inner lock	nett	\$	485.00
1pc	Rear tailgate inner rubber	nett	\$	220.00
1pc	Rear tailgate inner garnish	nett	\$	580.00
2pcs	Rear taillamp lower garnish @\$255.00	nett	\$	510.00
1pc	Rear bumper	nett	\$	1,450.00
1pc	Rear bumper side garnish @\$110.00	nett	\$	220.00
2pcs	Rear bumper parking sensor @\$275.00	nett	\$	550.00
2pcs	Rear bumper parking sensor rubber ring @\$15.00	nett	\$	30.00
1pc	Rear end panel	nett	\$	685.00
1pc	Rear end panel inner garnish	nett	\$	295.00
		nett		
			\$	7,200.00
	less 10%		\$	720.00
			\$	6,480.00
1set	Rear number plate & casing	s.nett	\$	30.00
	wiring		\$	80.00
	tuffkote		\$	120.00
	spray painting		\$	1,000.00
	labour charges		\$	1,000.00
	Total		\$	8,710.00

