

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

30/10/2021

Owner: NEO LAY HOON

AKK
08/11/21
monday
at 11 am

Not withair
L1 Pump &
Resurvey After Rainy
4-5 days

ESTIMATE TO REPAIR NISSAN SERENA - SMR3276C

1pc	Rear tailgate	1pc	nett	\$	1,850.00	✓
1pc	Rear tailgate windscreen mouldling	1pc	nett	\$	195.00	—
1pc	Rear tailgate "Highway Star" emblem	1pc	nett	\$	55.00	—
1pc	Rear tailgate "E-Power" emblem	1pc	nett	\$	75.00	—
1pc	Rear tailgate inner lock		nett	\$	485.00	?
1pc	Rear tailgate inner rubber		nett	\$	220.00	?
1pc	Rear tailgate inner garnish	1pc	nett	\$	580.00	X
2pcs	Rear taillamp lower garnish @\$255.00	1pc	nett	\$	510.00	X
1pc	Rear bumper	1pc	nett	\$	1,450.00	✓
1pc	Rear bumper side garnish @\$110.00	1pc	nett	\$	220.00	X
2pcs	Rear bumper parking sensor @\$275.00		nett	\$	550.00	?
2pcs	Rear bumper parking sensor rubber ring @\$15.00		nett	\$	30.00	?
1pc	Rear end panel		nett	\$	685.00	?
1pc	Rear end panel inner garnish		nett	\$	295.00	?
			nett			

less 10%


\$ 7,200.00
\$ 720.00
\$ 6,480.00

1set Rear number plate & casing

s.nett \$ 30.00 X

wiring
tuffkote
spray painting
labour charges
Total

\$ 80.00 151.
\$ 120.00 301
\$ 1,000.00 6001
\$ 1,000.00 5001
\$ 8,710.00



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: