

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.


Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

30/10/2021

Owner: NEO LAY HOON

ESTIMATE TO REPAIR NISSAN SERENA - SMR3276C

1pc	Rear tailgate	1742	net	\$	1,850.00	✓
1pc	Rear tailgate windscreen moulding		net	\$	195.00	—
1pc	Rear tailgate "Highway Star" emblem		net	\$	55.00	—
1pc	Rear tailgate "E-Power" emblem		net	\$	75.00	—
1pc	Rear tailgate inner lock		net	\$	485.00	✓
1pc	Rear tailgate inner rubber		net	\$	220.00	✓
1pc	Rear tailgate inner garnish		net	\$	580.00	✓
2pcs	Rear taillamp lower garnish @\$255.00		net	\$	510.00	✓
1pc	Rear bumper	1414	net	\$	1,450.00	✓
1pc	Rear bumper side garnish @\$110.00		net	\$	220.00	✓
2pcs	Rear bumper parking sensor @\$275.00	0232.00	net	\$	550.00	✓
2pcs	Rear bumper parking sensor rubber ring @\$15.00		net	\$	30.00	✓
1pc	Rear end panel		net	\$	685.00	✓
1pc	Rear end panel inner garnish	242	net	\$	295.00	✓
					nett	
					\$	7,200.00
less 10%					\$	720.00
					\$	6,480.00
1set	Rear number plate & casing		s.net	\$	30.00	✓
	wiring			\$	80.00	15/
	tuffkote			\$	120.00	30/
	spray painting			\$	1,000.00	600/
	labour charges			\$	1,000.00	500/
	Total			\$	8,710.00	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AIG
LKK-
08/11/21
Monday
at 11 am

Not wither
61 Rmg @ 4850/4
Resurvey After Rainy
4 days