

## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Reg No : 199405410K

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
	Cust No/Name	/LIM HAN CHUAN (LIN HANCHUAN)			
LIM HAN CHUAN (LIN HANCHUAN)	Reg No/Reg Date	SMK7001P / 06/05/201			
BLK 636 ANG MO KIO AVENUE 6	Date In/Mileage				
#05-5165	Chassis No	KNAF3416MK5036851			
SINGAPORE 560636		G4FGJH720102			
Contact No Mobile: 98188981	Make/Model	KIA/CERATO 1.6 A SR SX G335			
		ABP AURORA BLACK / WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
CSM00081	Cash	01/11/2021/ 15:22		442 / CocoLu		41879		
001100001		Description of Good	s / Services		Qty	<b>Unit Price</b>	Disc%	Amount
E PNT98000 SPRAY PAI E PNT88000 REMOVE & A 90000001 CHECK WIF A 10028901 TO CARRY M SUNDRY APPLY SEA B WHEELALIGN	INT FOR I INSTALL RING & EL OUT DIAG ALANT FOR	RH, FRT DOOR RH, WIN	NDMIRROR RH DER RH, WINI GLASS	DMIRROR RH 330 X	70 2 + 80			680_1920.00 780_1650.00 200_300.00 30.00 170_280.00 40.00,
M SUNDRY Sundry M PANEL-FEN M INSULATOR M PANEL ASS M HINGE ASS M HINGE ASS M BLACK TAR M MOULDING M W/STRIP	NDER,RH R-FENDER SY-FRONT SY-FRONT SY-DOOR PE-FR DR ASSY-FR ASSY-FR	DOOR,RH DOOR,RH LOWER,RH	^		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	430.00 27.00 1277.00 30.00 27.00 13.00 72.00 80.00 559.00	00.00 00.00 00.00 00.00 00.00 00.00 00.00	20.00, 430.00 27.00, 1277.00, 30.00 27.00 13.00, 72.00 80.00 559.00
Confirm & a	the Ron	lo Consultants hence notify pairer of the following: eyey before latter spray painting and damaged part(s) during resurve	/	fere (LKK)  11 21, 9.39cn	7//	PLR		
	<ul> <li>Parts pr</li> <li>Third pa</li> <li>No illega</li> <li>Supplent is subject</li> </ul>	ices are subject to confirmation irfy survey is on a "Without Prejud al modification(s) is allowed hentary item(s) must be resurveye at to final approval from Insurance	ice" basis		7% GST on To	Ne 6875. otal Payab	00	6,875.00 481.25 7,356.25
Authorized	signator	y and company stamp						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.