



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIU JIALIANG ERIC	Cust No/Name /LIU JIALIANG ERIC
BLK 309 JURONG EAST STREET 32	Reg No/Reg Date SKP996L / 21/05/201
#08-278	Date In/Mileage / 0
SINGAPORE 600309	Chassis No KNAF5416MK5027626
Contact No Mobile: 97510251	Engine No G4FGJH716118
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	01/11/2021/ 13:47	BLC	442 / Cocolu	41918

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 ? RENEW FRT BUMPER, REPAIR FRT FENDER LH 499 X 1				499 800.00
E PNT98000 ? SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH 350 X 1				480 350 700.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM 480				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY Sundry				20.00
M COVER-FR BUMPER / BR	1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER / BR	1.00	485.00	00.00	485.00
M COVER-FR BUMPER FOG LAMP, LH / BR	1.00	15.00	00.00	15.00
M GRILLE ASSY-RADIATOR ? x nn	1.00	328.00	00.00	328.00
M LAMP ASSY-FRONT FOG, LH ? x nn	1.00	303.00	00.00	303.00
M MOULDING-FRONT BUMPER, LH / BR	1.00	216.00	00.00	216.00
M LAMP ASSY-SIDE REPEATER, LH / BR	1.00	143.00	00.00	143.00
M ABSORBER-FRONT BUMPER ENERGY ? - BR	1.00	84.00	00.00	84.00
M AIR DUCT-FR BUMPER, LH ? - BR	1.00	14.00	00.00	14.00
M ULTRASONIC SENSOR ASSY-P.A.S ? x nn	1.00	163.00	00.00	163.00
M BRACKET-FR BUMPER UPR SIDE MTG ? x nn	1.00	22.00	00.00	22.00
M ORNAMENT-KIA NO.115 / KC	1.00	32.00	00.00	32.00
M LAMP ASSY-HEAD, LH / CUT	1.00	2210.00	00.00	2210.00

Steve (LKK)
2/11/21, 9:39am

00-11 AL
EXP 11-?
PIP
My BCL by
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

7% GST on **Nett** 6,318.00 442.26
Total Payable 6,760.26

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.