

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIU JIALIANG ERIC	Cust No/Name /LIU JIALIANG ERIC
BLK 309 JURONG EAST STREET 32	Reg No/Reg Date SKP996L / 21/05/201
#08-278	Date In/Mileage / 0
SINGAPORE 600309	Chassis No KNAF5416MK5027626
Contact No Mobile: 97510251	Engine No G4FGJH716118
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	01/11/2021/ 13:47	BLC	442 / CocoLu	41918

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, REPAIR FRT FENDER LH				800.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH				700.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY Sundry				20.00
M COVER-FR BUMPER	1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER	1.00	485.00	00.00	485.00
M COVER-FR BUMPER FOG LAMP,LH	1.00	15.00	00.00	15.00
M GRILLE ASSY-RADIATOR	1.00	328.00	00.00	328.00
M LAMP ASSY-FRONT FOG,LH	1.00	303.00	00.00	303.00
M MOULDING-FRONT BUMPER,LH	1.00	216.00	00.00	216.00
M LAMP ASSY-SIDE REPEATER,LH	1.00	143.00	00.00	143.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	00.00	84.00
M AIR DUCT-FR BUMPER,LH	1.00	14.00	00.00	14.00
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	163.00	00.00	163.00
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	00.00	22.00
M ORNAMENT-KIA NO.115	1.00	32.00	00.00	32.00
M LAMP ASSY-HEAD,LH	1.00	2210.00	00.00	2210.00

Confirm & accepted by

7% GST on	Nett 6318.00	6,318.00
		442.26
Total Payable		6,760.26

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.