

Tropical Tech Automobile Services

Blk 5032 Ang Mo Kio Avenue 3 #01-303 Industrial Park 2 Singapore 569535

Tel : 6481 7773 / 6481 1403 Fax : 6484 4978

E-mail : kennyphua@tropical-success-autocare.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd**
3, Anson Road, #16-00,
Springleaf Tower,
Singapore 079909

Estimate bill : TT 36 / 21 / TP / WT

Registration No : SLA6681Y

Attention : Motor Claims Third Party Department
Tel : 6222 2366
Fax : 6224 7175

Make / model : Toyota Estima

Mileage :

Date : 30 / 10 / 2021

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SMV5336D AND SLA6681Y ALONG CTE HEADING TOWARDS ANG MO KIO ON 27 OCTOBER 2021 AT ABOUT 1920HRS.

1pc	Rear bumper	715.90	Not m/s m	862.00	✓
1set	Rear bumper parktronic sensor kit		\$	280.00	X
1pc	Rear bumper towing cover (RH)		\$	69.00	X
1pc	Rear bumper reflector (RH)		\$	76.00	✓
1pc	Rear bumper side bracket (RH)	80.	\$	97.00	✓
	Sub A total :		\$	1,384.00	
	Less 25% discount :		\$	346.00	
	A total :		\$	1,038.00	

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear bumper, rear bumper parktronic sensor kit, rear bumper towing cover (RH), rear bumper reflector (RH), rear bumper side bracket (RH).

Heat / weld / beating rear end panel, held weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear bumper parktronic sensor fault error by HHT.

Undercoating on rear damaged portion.

Putty / primer application, spray painting on rear bumper, rear bumper parktronic sensors, rear bumper towing cover (RH) (Pearl White).

Grand final amount :

\$ 2,138.00

Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Not within
Hlep & 1st
Penny After Pain
1153.92
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: