



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21011146/Atf3e2	
			Date: 02/12/2021	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJJ 818L	Veh. Inspected	SMC 9873T
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D16992111	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	01/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	MR053REE104106110	Colour	WHITE
	Odometer	160587 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	CRUCERO	6 mm
	L/H Front Tyre	195/65 R15	CRUCERO	6 mm
	R/H Rear Tyre	195/65 R15	CRUCERO	6 mm
	L/H Rear Tyre	195/65 R15	CRUCERO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/10/2021	Inspection Date	03/11/2021
	Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	