

Our Job Ref No 308492359  
Date : 01/11/21

# ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6548 8156

## FINALIZATION FORM

To : LKK  
Attn : THEVAN  
: SHC 503E


Fax :

DOA: 27/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBD87533M
2. The finalized amount shall be:
  - (a) Spare Parts after List discount \_\_\_\_\_
  - (b) Labour Charges \_\_\_\_\_
  - Total for Part-By-Part Repair Cost** \_\_\_\_\_
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$5,800.00  
**Final Lumpsum Repair cost** \_\_\_\_\_
3. Estimated normal period for repairs: 3 working days
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :   
Name : THEVAN  
Date : 21/11/21

### For Official Use Only

| Item   | Amount      | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|-------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |             | YES                         |                        |         |
| 2. Loss of Income Paid                               | -           | N                           |                        |         |
| 3. Survey Fees                                       | -           | -                           |                        |         |
| 4. LTA Search Fee                                    | 7.49 / 2.00 | YES                         |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |             |                             |                        |         |
| 6 Overrun  |             |                             |                        |         |

Remarks:

\_\_\_\_\_  
\_\_\_\_\_



**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO **SHC 503E**  
 MAKE **HYUNDAI**  
 MODEL **IONIQ**

DATE: **27/10/2021**  
 MVA **JUMANI**  
 DOA: **27. Oct. 2021**

**NTUC**

| Qty | Parts Description/ Labour         | Type | Unit Price | Amount            |         |
|-----|-----------------------------------|------|------------|-------------------|---------|
|     |                                   |      |            | \$459.40          | cut     |
| 1   | REAR BUMPER ASSY                  |      |            | \$451.25          | cut     |
| 1   | REAR BUMPER CENTRE MLDG           |      |            | \$394.80          | resuc   |
| 1   | REAR BUMPER BEAM                  |      |            | \$41.45           | cut     |
| 1   | REAR BUMPER REFLECTOR RH          |      |            | \$22.00           | nic     |
| 10  | REAR BUMPER CLIPS                 |      |            | \$138.10          | resuc   |
| 1   | REAR BUMPER BEAM BRACKET RH       |      |            | \$108.00          | cut     |
| 1   | REAR BUMPER SIDE COVER RH         |      |            | \$55.80           | nic     |
| 1   | REAR BUMPER SIDE BRACKET RH       |      |            | \$1,768.30        | net     |
| 1   | REAR FENDERRLH                    |      |            | \$870.40          | scr     |
| 1   | TAILLAMP ASSY RH                  |      |            | \$41.45           | repair  |
| 1   | REFLECTOR RH                      |      |            | \$4,350.95        |         |
|     | <b>SUB TOTAL</b>                  |      |            | <b>\$4,350.95</b> |         |
|     | <b>LESS 20%</b>                   |      |            | <b>\$870.19</b>   |         |
|     | <b>DISCOUNTED TOTAL</b>           |      |            | <b>\$3,480.76</b> |         |
|     | REVERSE SENSOR                    |      |            | \$180.00          | NET/cut |
|     | ADVERTISEMENT LOGO – FENDER       |      |            | \$200.00          | NET/nic |
|     |                                   |      |            | <b>\$380.00</b>   |         |
|     | <b>Labour Charge</b>              |      |            | \$1,200.00        | 700     |
|     | PANEL BEATING                     |      |            | \$600.00          | 500     |
|     | SPRAY PAINT                       |      |            | \$500.00          | 20      |
|     | REMOVE/REFIX REVERSE SENSOR       |      |            | \$50.00           | 20      |
|     | CHECK WIRING                      |      |            | \$50.00           | 20      |
|     | TUFF KOTE                         |      |            | \$120.00          | 100     |
|     | REMOVE/ REFIX REAR UPHOLSERY REAR |      |            |                   |         |
|     | <b>TOTAL LABOUR</b>               |      |            | <b>\$2,520.00</b> |         |
|     | <b>ESTIMATE TOTAL</b>             |      |            | <b>\$6,365.20</b> |         |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Thuan@lkhauto.com*  
 822 35769  
 27/10/21 1615  
 3clays wp  
 LIS after repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.