

Our Job Ref No : 305492126  
Date : 28/10/21

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

## FINALIZATION FORM

To : LKK  
Attn : Mr THEVAN  
Vehicle Reg No. : SHC7951Z CCPL 23/10/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC --- GBF5872L
2. The finalized amount shall be:
- |   |                   |
|---|-------------------|
| (a) Spare Parts after List discount       | \$1,002.76        |
| (b) Labour Charges                        | \$620.00          |
| <b>Total for Part-By-Part Repair Cost</b> | <b>\$1,622.76</b> |
| (c.) Lumpsum Repair (if applicable)       |                   |
| Total for Lumpsum repair cost after Less: | 20%               |
| <b>Final Lumpsum Repair cost</b>          |                   |


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : MS. LOKE YY  
Tel : 62148355  
Fax : 65468156

Signature :   
Name : THEVAN  
Date : 2/11/21

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC7951Z

Make : HYUNDAI

Model : IONIQ(G3)

Date: 27/10/2021

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER SIDE BRACKET RH			\$55.80
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET RH			\$138.10
1	REAR BUMPER REFLECTOR LAMP RH			\$41.45
	SUB TOTAL			\$1,562.80
	LESS 20%			\$312.56
	DISCOUNTED TOTAL			\$1,250.24
1	REAR BUMPER RUBBER MAT			\$50.00
1	REAR BUMPER REVERSE SENSOR		-10%	\$180.00
				\$230.00
	Labour Charge			
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$60.00
	TOTAL LABOUR			\$1,060.00
	ESTIMATE TOTAL			\$2,540.24

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan@Lkhauto.com

82235769

27/10/21 1600

p/p bfr paint photo

2 days up

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305492126  
REGN NO : SHC7951Z  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 27.08.2020  
DATE/TIME IN : 27.10.2021 09:00  
ACCIDENT DATE : 23.10.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003 04-01-0104-2532-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64
0004 04-01-0104-1150-A	PROTECTOR MAT	1	50.00	2.00-	50.00
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60
0006 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1	180.00	10.00	162.00

SUB-TOTAL : 1,002.76

## JOB NATURE

0000 PB	PANEL BEATING SHC7951Z	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	REMOVE/ REFIX REVERSE SENSOR	20.00

SUB-TOTAL : 620.00

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 28.10.2021  
Time: 13:12:03  
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305492126  
REGN NO : SHC7951Z  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 27.08.2020  
DATE/TIME IN : 27.10.2021 09:0  
ACCIDENT DATE : 23.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT



Loke Wei Yiang

TOTAL : 1,622.76

MVA NAME & SIGNATURE

DATE:

28/10/21

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE: