

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0903/2021/JT
DATE : 3-Nov-21
WIP : 51397

Xiao Tony.

VEHICLE NOT IN WORKSHOP. SURVEY TBC
YOUR INSURED VEH NO : SMJ 4611 D

\$1522

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS JENNIFER QUEK SIEW LIAN
ADDRESS : 130 LOR K TELOK KURAU
#05-09
SINGAPORE 425769
TELEPHONE : HP +65 97389659
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100499740-04
VEHICLE NO : SLK 8495 C
MODEL CODE : AUDI A3 SB 1.0 TFSI
MODEL YEAR : 31/1/2017
ENGINE NO : CHZ 156722
CHASSIS NO : WAUZZZ8V1HA058056
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jul-21
PLACE OF ACCIDENT : OPPOSITE HIGH GATE CONDO



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLK 8495 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 ✓
3	TO REPSRAY REAR BUMPER.	\$ 900.00	550 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,422.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 8495 C

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Regis</i>	1	\$ 2,070.00	+
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	+
3	REAR BUMPER LOCKING MECHANISM - LH / RH <i>3 not ne</i>	2	\$ 28.00	+
4	REAR BUMPER ADAPTER - LH <i>3 ne n</i>	1	\$ 38.00	+
5	REAR BUPMER SPOILER	1	\$ 237.00	+
6	REAR LIGHT REFLECTOR - LH	1	\$ 30.00	+
7	REAR BUMPER REINFORCEMENT BEAM <i>3</i>	1	\$ 603.00	+
8	REAR BUMPER BRACKET - LH <i>3 ne n</i>	1	\$ 27.00	+
9	REAR BUMPER BRACKET - RH	1	\$ 29.00	+
10	REAR BUMPER GUIDE SECTION - LH	1	\$ 67.00	+
11	REAR PARKING AID SENSOR - INNER / OUTER <i>3 ne n</i>	2	TBC	+
12	REAR PARKING AID SENSOR SEAL RING	1	\$ 9.00	+
12	SUNDRIES <i>not ne</i>	1	\$ 200.00	+
TOTAL SPARE PARTS		:	\$ 3,531.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	
GRAND TOTAL		:	\$ 5,953.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lij

SURVEYED DATE

:

12/11/21

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 03 Days 

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT