

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0903/2021/JT
DATE : 03-Nov-21
WIP : 51397

VEHICLE NOT IN WORKSHOP. SURVEY TBC

YOUR INSURED VEH NO : SMJ 4611 D

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 11 Jan 22

OWNER'S NAME : MS JENNIFER QUEK SIEW LIAN
ADDRESS : 130 LOR K TELOK KURAU
#05-09
SINGAPORE 425769
TELEPHONE : HP +65 97389659
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100499740-04
VEHICLE NO : **SLK 8495 C**
MODEL CODE : AUDI A3 SB 1.0 TFSI
MODEL YEAR : 31/01/2017
ENGINE NO : CHZ 156722
CHASSIS NO : WAUZZZ8V1HA058056
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jul-21
PLACE OF ACCIDENT : OPPOSITE HIGH GATE CONDO

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLK 8495 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 500.00
3	TO REPSRAY REAR BUMPER.	\$	900.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 2,422.00	\$ 1,522.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 8495 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,070.00	
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	
3	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 28.00	
4	REAR BUMPER ADAPTER - LH	1	\$ 38.00	
5	REAR BUPMER SPOILER	1	\$ 237.00	
6	REAR LIGHT REFLECTOR - LH	1	\$ 30.00	
7	REAR BUMPER REINFORCEMENT BEAM	1	\$ 603.00	
8	REAR BUMPER BRACKET - LH	1	\$ 27.00	
9	REAR BUMPER BRACKET - RH	1	\$ 29.00	
10	REAR BUMPER GUIDE SECTION - LH	1	\$ 67.00	
11	REAR PARKING AID SENSOR - INNER / OUTER	2	TBC	
12	REAR PARKING AID SENSOR SEAL RING	1	\$ 9.00	
12	SUNDRIES	1	\$ 200.00	
TOTAL SPARE PARTS			\$ 3,531.00	\$ -
TOTAL LABOUR CHARGES			\$ 2,422.00	\$ 1,522.00
GRAND TOTAL			\$ 5,953.00	\$ 1,522.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT