



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE			Ref: CC4/ASM21011163/Aea3q2 Date: 20/05/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	FBR 122M	<b>Veh. Inspected</b>	SMC 8521R
	<b>Policy No.</b>	P2382820	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	S1M03L37	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	01/11/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HYUNDAI ELANTRA	<b>c.c</b>	1591
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
	<b>Chassis No.</b>	KMHD841CMJU727824	<b>Colour</b>	GREY
	<b>Odometer</b>	72425 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
	<b>L/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
	<b>R/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm
	<b>L/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  DAMAGES SEE DETAILS			
<b>5. General Information</b>				
	<b>Accident Date</b>	28/10/2021	<b>Inspection Date</b>	01/11/2021
	<b>Survey held at</b>	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	