

LEE SHENG AUTO PTE LTD

Page 1 / 2

1, Kaki Bukit Ave 6, Autobay@KakiBukit
#01-60/58, Singapore 417883
Tel No. : 67477333 Fax No. : 67457138
E-Mail : leesheng@singnet.com.sg
Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. MOHAMMAD NAZMI BIN MASAGOES HASSAN
BLK 338C ANCHORVALE CRESCENT #07-35
singapore 543338

Attention : Motor Claim Department
Contact : 90626283

Estimate : ES001549

Date : 11/10/2021
Vehicle Num. : SMU 6813 S
Make/Model : TOYOTA PICNIC-2006
Chassis/Eng# : JTEGH23B400023146/1AZ5549410
Accident Date : 21/10/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT FENDER RH <i>Dented</i>		685.00 <i>✓</i>
2.	1	FRONT FENDER INNER SHIELD; REPAIR <i>torn</i>		185.00 <i>✓</i>
3.	10	FRONT FENDER INNER SHIELD CLIPS <i>new</i>	3.50	35.00 <i>✓</i>
4.	1	FRONT BUMPER <i>Distorted</i>		785.00 <i>✓</i>
5.	1	FRONT BUMPER REINFORCEMENT <i>new</i>		385.00 <i>✓</i>
6.	1	FRONT BUMPER RETAINER LH <i>new</i>		24.50 <i>✓</i>
7.	1	FRONT BUMPER RETAINER RH <i>new</i>		24.50 <i>✓</i>
8.	1	FRONT BUMPER FOG LAMP RH <i>new</i>		250.00 <i>✓</i>
9.	1	FRONT BUMPER FOG LAMP BRACKET RH <i>new</i>		85.50 <i>✓</i>
10.	1	FRONT BUMPER FOAM <i>new</i>		78.00 <i>✓</i>
11.	1	FRONT BUMPER BRACKET RH <i>new</i>		26.80 <i>✓</i>
12.	1	SPARE TANK <i>new</i>		250.00 <i>✓</i>
13.	1	BONNET <i>new</i>		1,475.00 <i>✓</i>
14.	1	GRILLE		450.00 <i>✓</i>
15.	1	BONNET LOCK		185.00 <i>✓</i>
16.	1	BONNET HINGE RH <i>new</i>		95.00 <i>✓</i>
17.	1	BONNET HINGE LH <i>new</i>		95.00 <i>✓</i>
18.	1	SUPPORT PANEL <i>new</i>		480.00 <i>✓</i>
19.	1	FRONT BUMPER UNDER COVER <i>new</i>		450.00 <i>✓</i>
20.	1	VVTI EMBLEM <i>new</i>		38.00 <i>✓</i>
21.	1	TOYOTA LOGO <i>new</i>		38.00 <i>✓</i>

List TotalS\$:

6,120.30

25.00% Discount S\$:

1,530.08

4,590.22

*Headlamp**575 ✓**at ✓*

CONTINUE / ...

LEE SHENG AUTO PTE LTD

Page 2 / 2

1, Kaki Bukit Ave 6, Autobay@KakiBukit
#01-60/58, Singapore 417883
Tel No. : 67477333 Fax No. : 67457138
E-Mail : leesheng@singnet.com.sg
Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. MOHAMMAD NAZMI BIN MASAGOES HASSAN
BLK 338C ANCHORVALE CRESCENT #07-35
singapore 543338

Attention : Motor Claim Department

Contact : 90626283

Estimate : ES001549

Date : 11/10/2021
Vehicle Num. : SMU 6813 S
Make/Model : TOYOTA PICNIC-2006
Chassis/Eng# : JTEGH23B400023146/1AZ5549410
Accident Date : 21/10/2021
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
KNOCKING, JACKING FRONT PORTION
SPRAY FRONT BONNET, FENDER, BUMPER, SUPPORT
WIRING
ALIGNMENT
ANTI RUSH ON AFFECTED AREA

~~1,200.00~~ 400
~~1,500.00~~ 400
~~50.00~~ 30
~~80.00~~ 4
~~250.00~~ 50

Labour Total S\$:

3,080.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
1/s 01/11/21
04 Days

Total S\$: 7,670.22

LEE SHENG AUTO PTE LTD