



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Khng Yong Meng Edmund
	Reg No/Reg Date	SKF9138R / 26/06/201
	Date In/Mileage	/ 80700
	Chassis No	KNAPH81BMJ5465570
	Engine No	D4HBJH373831
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	02/11/2021/ 08:44	TLE	261 / Edwin Caina	41925			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FR BUMPER , BONNET & FR SUPPORT PNL					400			800
REPAIR LHF FENDER								
E PNT98000								1050.00
RESPRAY FR BUMPER , BONNET & LHF FENDER					350			700
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								?
M SUNDRY								80.00
TOP UP AC GAS								?
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM								120.00
A 10028901								50.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								50.00
M SUNDRY								80.00
SUPPLY FR NUMBER PLATE WITH CASING								80.00
E PNT88000								60.00
REMOVE & REFIT FR PARKING ASSIST SENSOR					40			60.00
M SUNDRY								20.00
SUPPLY BODY PNL SEALANT								20.00
M SUNDRY								2500.00
Sundries								?
M SUNDRY								
RE-WRAPPING ACCIDENT PORTION AREAS					1.00	1654.00	20.00	1323.20
M PANEL ASSY-HOOD					1.00	87.00	20.00	69.60
M HINGE ASSY-HOOD,LH					1.00	87.00	20.00	69.60
M HINGE ASSY-HOOD,RH					1.00	1.00	20.00	10.40
M CLIP-HOOD INSULATING PAD MTG					13.00	27.00	20.00	21.60
M STRIP ASSY FR-HOOD					1.00	104.00	20.00	83.20
M LATCH ASSY-HOOD					1.00	186.00	20.00	148.80
M COVER ASSY-RADIATOR GRILLE UPR					1.00	673.00	20.00	538.40
M GRILLE ASSY-RADIATOR					1.00	561.00	20.00	448.80
M COVER-FR BUMPER UPR					1.00	20.00	20.00	16.00
M MOULDING-FRT BPR LICENSE PLATE								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/Khng Yong Meng Edmund</td></tr> <tr> <td>Reg No/Reg Date</td><td>SKF9138R / 26/06/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 80700</td></tr> <tr> <td>Chassis No</td><td>KNAPH81BMJ5465570</td></tr> <tr> <td>Engine No</td><td>D4HBJH373831</td></tr> <tr> <td>Make/Model</td><td>KIA/SORENTO 2.2 A D SX SR GD57</td></tr> <tr> <td>Colour/Trim</td><td>MST METAL STREAM / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Khng Yong Meng Edmund	Reg No/Reg Date	SKF9138R / 26/06/201	Date In/Mileage	/ 80700	Chassis No	KNAPH81BMJ5465570	Engine No	D4HBJH373831	Make/Model	KIA/SORENTO 2.2 A D SX SR GD57	Colour/Trim	MST METAL STREAM / WK SATURN BLACK
Cust No/Name	/Khng Yong Meng Edmund														
Reg No/Reg Date	SKF9138R / 26/06/201														
Date In/Mileage	/ 80700														
Chassis No	KNAPH81BMJ5465570														
Engine No	D4HBJH373831														
Make/Model	KIA/SORENTO 2.2 A D SX SR GD57														
Colour/Trim	MST METAL STREAM / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	02/11/2021/ 08:44	TLE	261 / Edwin Caina	41925			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MOULDING-FRONT BUMPER LWR,LH				1.00	89.00	20.00	71.20
M	MOULDING-FRONT BUMPER LWR,RH				1.00	89.00	20.00	71.20
M	LIP-FRONT BUMPER				1.00	56.00	20.00	44.80
M	SKID PLATE-FR BUMPER				1.00	111.00	20.00	88.80
M	GRILLE-FRONT BUMPER				1.00	191.00	20.00	152.80
M	ABSORBER-FRONT BUMPER ENERGY				1.00	117.00	20.00	93.60
M	STIFFENER ASSY-FR BUMPER LWR				1.00	117.00	20.00	93.60
M	BRACKET-FR BUMPER SIDE,LH				1.00	17.00	20.00	13.60
M	BRACKET-FR BUMPER SIDE,RH				1.00	17.00	20.00	13.60
M	ULTRASONIC SENSOR-S.P.A.S				4.00	187.00	20.00	598.40
M	LAMP ASSY-HEAD,LH				1.00	2743.00	20.00	2194.40
M	BEAM COMPLETE-FR BUMPER				1.00	551.00	20.00	440.80
M	CARRIER ASSY-FRONT END MODULE				1.00	760.00	20.00	608.00

SURVEYOR NAME: Steve (LKK) 2/11/21, 9.39amSURVEYOR SIGNATURE: 00- N1 ALDATE: Excess - ?REMARKS: P/P
By Bel sy
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

* To resurvey before/after spray painting

Confirm & accepted by:

- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

	Nett	13,304.40
7% GST on	13304.40	931.31
Total Payable		14,235.71

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.