



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Khng Yong Meng Edmund
	Reg No/Reg Date	SKF9138R / 26/06/201
	Date In/Mileage	/ 80700
	Chassis No	KNAPH81BMJ5465570
	Engine No	D4HBJH373831
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	01/11/2021/ 17:57	TLE	261 / Edwin Caina	41925			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FR BUMPER , BONNET & FR SUPPORT PNL								
REPAIR LHF FENDER								
E PNT98000								1050.00
RESPRAY FR BUMPER , BONNET & LHF FENDER								
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								
M SUNDRY								80.00
TOP UP AC GAS								
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
SUPPLY FR NUMBER PLATE WITH CASING								
E PNT88000								80.00
REMOVE & REFIT FR PARKING ASSIST SENSOR								
M SUNDRY								60.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								20.00
Sundries								
M	PANEL ASSY-HOOD				1.00	1654.00	20.00	1323.20
M	HINGE ASSY-HOOD,LH				1.00	87.00	20.00	69.60
M	HINGE ASSY-HOOD,RH				1.00	87.00	20.00	69.60
M	CLIP-HOOD INSULATING PAD MTG				13.00	1.00	20.00	10.40
M	STRIP ASSY FR-HOOD				1.00	27.00	20.00	21.60
M	LATCH ASSY-HOOD				1.00	104.00	20.00	83.20
M	COVER ASSY-RADIATOR GRILLE UPR				1.00	186.00	20.00	148.80
M	GRILLE ASSY-RADIATOR				1.00	673.00	20.00	538.40
M	COVER-FR BUMPER UPR				1.00	561.00	20.00	448.80
M	MOULDING-FRT BPR LICENSE PLATE				1.00	20.00	20.00	16.00
M	MOULDING-FRONT BUMPER LWR,LH				1.00	89.00	20.00	71.20
M	MOULDING-FRONT BUMPER LWR,RH				1.00	89.00	20.00	71.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Khng Yong Meng Edmund
	Reg No/Reg Date	SKF9138R / 26/06/201
	Date In/Mileage	/ 80700
	Chassis No	KNAPH81BMJ5465570
	Engine No	D4HBJH373831
	Make/Model	KIA/SORENTO 2.2 A D SX SR GDS7
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	01/11/2021/ 17:57	TLE	261 / Edwin Caina	41925
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	LIP-FRONT BUMPER	1.00	56.00	20.00	44.80
M	SKID PLATE-FR BUMPER	1.00	111.00	20.00	88.80
M	GRILLE-FRONT BUMPER	1.00	191.00	20.00	152.80
M	ABSORBER-FRONT BUMPER ENERGY	1.00	117.00	20.00	93.60
M	STIFFENER ASSY-FR BUMPER LWR	1.00	117.00	20.00	93.60
M	BRACKET-FR BUMPER SIDE,LH	1.00	17.00	20.00	13.60
M	BRACKET-FR BUMPER SIDE,RH	1.00	17.00	20.00	13.60
M	ULTRASONIC SENSOR-S.P.A.S	4.00	187.00	20.00	598.40
M	LAMP ASSY-HEAD,LH	1.00	2743.00	20.00	2194.40
M	BEAM COMPLETE-FR BUMPER	1.00	551.00	20.00	440.80
M	CARRIER ASSY-FRONT END MODULE	1.00	760.00	20.00	608.00

Estimate

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

Confirm & accepted by

	Nett	10,804.40
7% GST on	10804.40	756.31
Total Payable		11,560.71

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.